

# Preliminary Site Investigation

Gilles Plains TAFE

# Preliminary Site Investigation

Gilles Plains TAFE

Client: Renewal SA

ABN: 86 832 349 553

Prepared by

**AECOM Services Pty Ltd**

Level 28, 91 King William Street, Adelaide SA 5000, Australia

T +61 8 7223 5400 F +61 8 7223 5499 [www.aecom.com](http://www.aecom.com)

ABN 46 000 691 690

27-Jul-2019

Job No.: 60603737

AECOM in Australia and New Zealand is certified to ISO9001, ISO14001 AS/NZS4801 and OHSAS18001.

© AECOM Services Pty Limited. All rights reserved.

No use of the contents, concepts, designs, drawings, specifications, plans etc. included in this report is permitted unless and until they are the subject of a written contract between AECOM Services Pty Limited (AECOM) and the addressee of this report. AECOM accepts no liability of any kind for any unauthorised use of the contents of this report and AECOM reserves the right to seek compensation for any such unauthorised use.

## Document Delivery

AECOM Services Pty Limited (AECOM) provides this document in either printed format, electronic format or both. AECOM considers the printed version to be binding. The electronic format is provided for the client's convenience and AECOM requests that the client ensures the integrity of this electronic information is maintained. Storage of this electronic information should at a minimum comply with the requirements of the Electronic Transactions Act 2002.

## Quality Information

Document Preliminary Site Investigation


Ref 60603737

Date 27-Jul-2019

Prepared by Mark Vial

Reviewed by Nicola McGunnigle

### Revision History

Rev	Revision Date	Details	Authorised	
			Name/Position	Signature
B	27-Jul-2019	Final Report	Mark Vial Professional Environmental Scientist	

## Table of Contents

Executive Summary	i
1.0 Introduction	1
1.1 Background	1
1.2 Objectives	1
1.3 Scope of works	1
2.0 Site Identification and Zoning	2
3.0 Site Description and Current Land Use	2
4.0 Surrounding Land Uses	3
5.0 Environmental Setting	3
5.1 Topography	3
5.2 Geology	4
5.3 Hydrology	4
5.4 Hydrogeology	4
5.4.1 Regional	4
5.4.2 Registered Groundwater Bores	4
6.0 Site Inspection	6
6.1 Site Setting and Surrounding Environment	6
6.2 Property Development	6
6.2.1 Buildings and Infrastructure	6
6.2.2 Drainage	8
6.2.3 Services	8
6.2.4 Aboveground and underground fuel storage	8
6.2.5 Settlement Tanks	8
6.3 Other Observations	8
6.4 Personnel Interviews	9
7.0 Site History	10
7.1 Past and Current Site Ownership and Occupancy	10
7.2 Historical Aerial Photography Review	10
7.3 Public Records	13
7.3.1 SA EPA Section 7 Public Register	13
7.3.2 SA EPA Site Contamination Index	13
7.3.3 EPA Authorisations (Licences) Index	14
7.3.4 Environmental Protection and Clean Up Orders	14
7.3.5 Dangerous Substances Licence Search	14
7.4 Previous Environmental Reports	15
7.5 Asbestos Register	15
8.0 Data Gaps	16
9.0 Preliminary Conceptual Site Model	17
9.1 Elements of a conceptual site model	17
9.2 Identified Potentially Contaminating Activities	17
9.3 Potential transport mechanisms and exposure routes	20
9.4 Potential receptors	20
9.5 Potential exposure pathways	20
10.0 Conclusion	26
11.0 References	27
12.0 Limitations	28
Appendix A	
Figures	A
Appendix B	
Historical Building Plans	B
Appendix C	
Site Photographs	C

Appendix D	
Asbestos Reports	D
Appendix E	
Site Topography	E
Appendix F	
Groundwater Data	F
Appendix G	
Certificates of Title	G
Appendix H	
Historical Aerial Photographs	H
Appendix I	
SA EPA Section 7 Search	I
Appendix J	
Dangerous Substances Licence Search	J

## Executive Summary

AECOM Australia Pty Ltd (AECOM) was engaged to undertake a Preliminary Site Investigation (PSI) at the Gilles Plains TAFE SA (Technical and Further Education) campus, located at Blacks Road, Gilles Plains, SA (the site).

It is understood that the PSI is intended to support rezoning of the site.

The objectives of the PSI were to identify potentially contaminating activities (PCA) and associated chemicals of potential concern (COPC) relating to the site and to review each PCA with regard to the potential risks to human health for both the current (commercial) and potential (low density residential) land uses.

The works conducted as part of the PSI included a site inspection, site history review, historical report review and conceptual site model development.

The site is located in Gilles Plains, approximately 9.5 kilometres north north-east of the Adelaide CBD. The site is approximately square in shape and is 8.085 hectares in size. Currently Gilles Plains TAFE operates at the centre of the site, comprising five main buildings utilised for applied science, building studies, dental studies, administration and a former cafeteria. A number of smaller buildings are also located on site and utilised for amenities, distribution, flammable liquids storage, aquaculture storage and farriery workshop. The northern portion of the site is currently utilised for agricultural activities (grazing) with associated sheds. The remainder of the site consists of a bituminised road and associated car parks, maintained lawns and large mature trees. The site is located directly adjacent to residential properties to the north, public institutions and sporting oval to the south and roads to the east and west.

Soils at the site are expected to consist of brown clays and limestone. Groundwater is expected to present at depths between 5-10 m below ground level (bgl). No groundwater wells are present at the site.

A site history assessment indicated that the site has been associated with TAFE activities since 1979. Prior to this time the site was vacant and was utilised for low scale agriculture activities (cropping land).

Based on findings of the site history review and site inspection, it is unlikely any unacceptable risk to human health exists based on the site's current commercial use, providing that any intrusive or maintenance works are undertaken in accordance with standard occupational health and safety protocols.

If the site use is to potentially be changed to low density residential, and assuming the settlement tanks and identified ACMs are removed in accordance with industry standards, further investigations are warranted to assess risk to human health associated with the following identified PCAs:

- Chemical Storage;
- Former spray painting area;
- Historical and current low scale agriculture;
- Possible herbicide and pesticide use in the vicinity of on-site buildings;
- Fill or soil importation; and
- Sump area.

It is noted that the identified PCAs (with the exception of spray painting) at the site are not included in the PCAs defined in Part 1 of Schedule 3 of the Environment Protection Regulations 2009. The identified PCAs are considered as having a low significance or highly localised and are unlikely to preclude the intended future land use.

## 1.0 Introduction

### 1.1 Background

Renewal SA engaged AECOM Australia Pty Ltd (AECOM) to undertake a Preliminary Site Investigation (PSI) at the Gilles Plains TAFE SA (Technical and Further Education) campus, located at Blacks Road, Gilles Plains, South Australia (the site).

It is understood that the PSI is intended to support rezoning of the site.

The Gilles Plains TAFE SA campus covers an approximate area of 8.08 hectares. The campus was established in 1971 and included facilities for courses in veterinary and applied sciences, dental studies, aquaculture and agricultural activities<sup>1</sup>.

### 1.2 Objectives

- To identify potentially contaminating activities (PCAs) and associated chemicals of potential concern (COPC) relating to the site; and
- Review each PCA in regards to potential risks to human health for both the current (commercial) and potential (low density residential) future land use.

### 1.3 Scope of works

The scope of works undertaken for the project is outlined below:

- Review of available historical information provided by Renewal SA:
  - Historical building plans from DPTI
  - Historical aerial photographs (10 year intervals from 1949 to present)
  - Asbestos register
  - Safe Work SA Dangerous Substances Licence Search
  - Previous investigations on nearby sites
- A desktop assessment including the following information:
  - Site identification and zoning
  - Site description and current land use
  - Surrounding land use
  - Current and historical Certificates of Title (CTs)
  - Review of historical aerial photographs and recent Nearmap images
  - Topography and drainage
  - Soils, geology and hydrogeology
  - Review of public records (SA EPA Section 7, Site Contamination Index for nearby Section 83A notifications, environmental protection and clean up orders, authorisations, dangerous substance licences)
  - Review of surrounding investigations
- A site walkover detailing current site conditions.
- Compilation of a PSI report documenting the findings of the above and presenting a preliminary Conceptual Site Model (this report).

---

<sup>1</sup> TAFE SA, Gilles Plains, Government of South Australia, <https://www.tafesa.edu.au>

## 2.0 Site Identification and Zoning

Site identification details and background information are summarised in **Table 2-1**. The site location is shown on Figure 1 (**Appendix A**).

**Table 2-1 Site Identification**

Item	Description
Facility Name	Gilles Plains TAFE
Facility Address	33 Blacks Road, Gilles Plains, 5086, South Australia
Certificate of Title	CT 5519/164
Section Plan	Section 788
Hundred	Yatala
Site Coordinates	Lat: -34.8519841 Long: 138.6519704
Area of Site	8.085 hectares
Current Site Owner	Urban Renewal Authority
Current Site Use	TAFE SA
Local Government Authority	City of Port Adelaide Enfield
Current Zoning	The site is located in the City of Port Adelaide Enfield and is zoned District Centre according to the Port Adelaide Enfield Council Development Plan (consolidated 6 February 2018) <sup>2</sup> .
Previous Environmental investigations	None known
Potential Site Use	Residential

## 3.0 Site Description and Current Land Use

The site layout and key features are detailed in **Figure 2 (Appendix A)**.

The site is roughly square in shape and fenced along its boundaries. The site is adjacent to residential properties to the north, public institutions with associated sporting oval to the south and roads to the east and west (followed by residential properties). The main site access is along its eastern boundary from Blacks Road.

Based on building plans last modified in February 2018 (attached as **Appendix B**), five large buildings exist in the centre of the site (Building 1, 2, 3, 4 and 4A). These buildings are currently listed for:

- Building 1 – Administration, Resource and General Teaching
- Building 2 – Dental Studies
- Building 3 – Theatre & Cafeteria
- Building 4 – Veterinary & Applied Science
- Building 4A – Building Studies

There are five smaller buildings located across the site which are currently listed for:

<sup>2</sup> Government of South Australia, Department of Planning, Transport and Infrastructure (DPTI), 2018, Port Adelaide Enfield Council development plan- consolidated 6 February 2018, webpage last updated 16 March 2018, viewed 23 April 2019, [www.dpti.sa.gov.au/\\_\\_data/assets/pdf\\_file/0005/295817/Port\\_Adelaide\\_Enfield\\_Council\\_Development\\_Plan.pdf](http://www.dpti.sa.gov.au/__data/assets/pdf_file/0005/295817/Port_Adelaide_Enfield_Council_Development_Plan.pdf)

- Building 7 – Student Amenities, located adjacent south of Building 3
- Building 10 – Distribution centre, located to the south west of Building 4
- Building 11 – Flammable liquids store, located to the east of Building 4
- Building 12 – Storage aquaculture, located to the east of Building 4A
- Building 13 – Farriery workshop, located to the east of Building 4A

There are five sheds (SH4, SH5, SH7, SH9 and SH23) located adjacent to the northern boundary, currently utilised for car parking and storage associated with the agricultural land which is located between the buildings and in the north western portion of the site.

There are also a number of smaller sheds located to the west of Building 4 and 4A. These are mainly used for storage for the building studies building, and SH16 is currently used as an aviary.

Historical plans identify two settlement tanks on the southern side of Building 3, which are associated with the cafeteria.

Carparks and a bitumen road surround the main building complex<sup>3</sup>.

## 4.0 Surrounding Land Uses

Land uses in the vicinity of the site based on the Property Location Browser, viewed 18 April 2019<sup>4</sup>, include:

- Residential properties are situated across roads to the east and west from the site.
- Residential properties are situated adjacent to the north, which is followed by agricultural land (grazing) and the Institute of Medical and Veterinary Sciences (situated 300m to the north).
- Public institutions (Royal Society for the Blind, Independent Living Centre and Minda ASSIST Therapy) are located directly to the south from the site boundary. There is also an associated sporting oval to the institutions.
- The small recreation/reserve identified areas closest to the site include Hedge Row Reserve (located 75m to the west) and Roy Amer Reserve (located 350m to the south-west).
- Educational facility (St Paul's College) is situated 200 m north-east from the site.
- Retail and commercial properties are situated 240m to the south-east.
- The closest service station has been identified 450m to the south of the site.

A search of the South Australian Heritage Places database found no listed heritage places within the suburb boundaries of Gilles Plains.

## 5.0 Environmental Setting

### 5.1 Topography

A map showing the regional topography of the site is presented in **Appendix E**. The site is situated approximately 80 to 85 m Australian Height Datum and slopes gently to the south.<sup>5</sup> The site inspection noted that the site topography was undulating and slopes towards the south west corner.

---

<sup>3</sup> Department of Planning, Transport and Infrastructure Government of South Australia, Drawing Title: TAFE SA Adelaide North Gilles Plains Campus, Blacks Road, Gilles Plains, 5086, created by J Sutton 1996, Modified by T Tan February 2018, Audited by A. Bryant July 2007, SAMIS no. 01503.

<sup>4</sup> Generalised Land Use, 2017: <http://maps.sa.gov.au/plb/>

<sup>5</sup> Department for Environment and Water, 2017, NatureMaps, viewed 18 April 2019, <http://spatialwebapps.environment.sa.gov.au/naturemaps>

## 5.2 Geology

Site maps produced from the SARIG online database showing regional geology (1:100,000 scale) and metropolitan soil layers surrounding Adelaide are presented in **Appendix E**<sup>6</sup>.

The SARIG online database, and the 1:100,000 scale geological map of Adelaide, indicate that the Keswick Clay (Qpas) is the main geological unit at and surrounding the site<sup>7</sup>.

The dominant soil type at and surrounding the site appears to be Black Earths (BE) according to both the SARIG online database and the Soil Association Map of the Adelaide Region. Black Earth soils are black to dark grey clay soils with coarse blocky structure over brown or mottled clay, variable lime and cracking soil<sup>8</sup>.

## 5.3 Hydrology

A map of hydrological features within 2 km of the site (attached as **Appendix E**<sup>9</sup>) indicates that no hydrological features are present on the site.

A number of artificial perennial lakes are present more than 500 m from east from the site. Water courses including Dry Creek and River Torrens are more than 1 km north and south of the site respectively. The Hope Valley Reservoir is located approximately 2.5 km east of the site.

## 5.4 Hydrogeology

### 5.4.1 Regional

Maps produced from the SARIG online database showing the expected depth and salinity of shallow groundwater are provided in **Appendix E**<sup>10</sup> and indicate shallow groundwater approximately 5-10 m below ground level. The expected salinity of shallow groundwater is expected to be between 1500-3000 mg/L.

Regional groundwater in the uppermost quaternary aquifer is generally expected to be flowing in a westerly direction towards Gulf St Vincent<sup>11</sup>. The direction of groundwater flow in the immediate vicinity of the site cannot be determined as there are no known historical reports for the site. A groundwater investigation was conducted by AECOM at a site located within 1 km of the former Gilles Plains TAFE. Groundwater at this nearby site is situated in fractured rock geology and groundwater flow appears to be highly dependent on local mechanisms of preferential recharge and the proximity of the site to Dry Creek (approximately 150 m).

### 5.4.2 Registered Groundwater Bores

A summary of registered groundwater bores on and within 2 km of the site is provided in **Appendix F**<sup>12</sup>.

No registered bores exist at the site or in the immediate vicinity. The nearest registered bore is located approximately 350 m north-northeast from the site and is noted to be abandoned.

166 registered bores exist within a 2 km radius of the site, of these 33 are listed as abandoned or backfilled and only three are listed as operational. The status of the remaining 66 bores is unknown. The purpose of registered bores listed is summarised in **Table 5-1**

All listed bores were installed to depths of between 2.5 to 196 m depth. The nearest bore potentially utilised for extractive purpose is located 410 m west-north-west from the site. This bore is an observational/recreational bore installed to 17 m depth in 1992, targeting the Hindmarsh clay aquifer.

<sup>6</sup> SARIG, 2019, South Australian Resources Information Gateway, viewed 23 April 2019 <https://map.sarig.sa.gov.au/>

<sup>7</sup> Department for Manufacturing, Innovation, Trade, Resources and Energy, 2011, Adelaide 1:100000 Scale, Map SI5409, Sheet 6628

<sup>8</sup> Taylor, J.K et al., Department of Mines SA, 1972, Soil Association Map of the Adelaide Region,

<sup>9</sup> SARIG, 2019, South Australian Resources Information Gateway, viewed 23 April 2019 <https://map.sarig.sa.gov.au/>

<sup>10</sup> SARIG, 2019, South Australian Resources Information Gateway, viewed 23 April 2019 <https://map.sarig.sa.gov.au/>

<sup>11</sup> Gerges, N., Department of Water, Land and Biodiversity Conservation, 2006, Report DWLBC 2006/10 – Overview of the Hydrogeology of the Adelaide Metropolitan Area, June 2006.

<sup>12</sup> WaterConnect, 2019, Groundwater Data Online Database, Department for Environment and Water, Government of South Australia, viewed 17 April 2019, <https://www.waterconnect.sa.gov.au/GD>

There are six investigation wells located between 960 m and 1020 m north-east from the site, with recorded standing water level of 9.5-17 m depth in 2012. The targeted aquifer and current status for these wells is not listed.

**Table 5-1: Summary of Registered Bores**

Purpose	Count
Construction Materials	1
Domestic	2
Industrial	1
Investigation	37
Irrigation	1
Monitoring	6
Observation	1
Unknown or not listed	51

## 6.0 Site Inspection

AECOM carried out a site inspection on 12 April 2019. Plates are provided in **Appendix C**.

### 6.1 Site Setting and Surrounding Environment

The site is accessed by two driveways along its eastern boundary off Blacks Road (**Plate 1**) and is securely fenced along its northern, southern and western boundaries.

A bitumen road encircles the five main site buildings in the centre of the site, connecting these with the two site entrances off Blacks Road. The bitumen road is generally in good condition with only minor cracking in some areas (**Plate 2**). Two large bitumen sealed car parks exist north and south of the main site buildings (**Plate 3 & 4**), which are summarised in **Table 6-1** below and shown on Figure 2 (**Appendix A**). The northern portion of the site comprises agriculture pens which extend along the whole northern boundary and partially down the western boundary (**Plate 5 & 6**). Access to these areas was limited as an escort was required, however no current sheep dips were apparent or any visual evidence of historical dips. A large, evidently irrigated, grassed area is present in the eastern portion of the site (**Plate 7**). Numerous well-maintained gardens and mature trees exist across the site.

The site is undulating and slopes towards the south west corner of the property. A penned south-west corner area of the site is used as an exercise area for dogs. A large stockpile of mulched bark chips was also present in this area (**Plate 8**).

Residential properties are directly adjacent the site to the north but are securely fenced from the site (**Plate 5**). Residential properties are present to the east across Blacks Road. Disability SA is located to the south of the site and consists of a number of brick buildings and a large recreational sporting ground (**Plate 9**). Residential properties are present to the west across Sudholz Road.

### 6.2 Property Development

#### 6.2.1 Buildings and Infrastructure

A summary of the main buildings and infrastructure on site is provided in **Table 6-1**.

**Table 6-1: Summary of Buildings on-site**

Building	Description	Plates
Building 1 – Administration Building	<ul style="list-style-type: none"> <li>North-east within central building complex</li> <li>Administration, resources and general teaching.</li> <li>Includes cleaner's room.</li> <li>A child care is present in the northern portion of the building. It is unclear whether it is still in use, no children were present on the day of the inspection.</li> </ul>	<b>Plate 10</b>
Building 2 – Dental Studies Building	<ul style="list-style-type: none"> <li>East within central building complex</li> <li>Used for para dental studies and is an operational dental clinic.</li> <li>Access limited during site inspection as still used for operational dental practice.</li> <li>Plant room (Shed 21) attached to the east of building.</li> <li>No chemical storage observed in plant room.</li> </ul>	<b>Plate 11</b>
Building 3 – Theatre & Cafeteria Building	<ul style="list-style-type: none"> <li>South-east within central building complex</li> <li>Theatre and cafeteria,</li> <li>Cafeteria is closed down and building is largely vacant.</li> </ul>	
Building 4 – Veterinary & Applied Science Building	<ul style="list-style-type: none"> <li>South-west within central building complex</li> <li>Veterinary and applied sciences</li> <li>Contains a number of laboratories.</li> </ul>	<b>Plate 12</b> <b>Plate 13</b> <b>Plate 14</b>

Building	Description	Plates
	<ul style="list-style-type: none"> <li>Access limited as escort is required.</li> <li>Maintenance storage room and cylinder storage located in western side of building.</li> </ul>	<b>Plate 15</b>
Building 4A – Building Studies Area	<ul style="list-style-type: none"> <li>North-west within central building complex</li> <li>Formerly building studies now largely vacant and used for storage of bulk materials, office supplies and other miscellaneous hard materials.</li> <li>Former workshop building repurposed for aquaculture.</li> <li>Used to house sign industry training, believed to be associated with the use of paints, and a bricklaying, tiling and plastering workshop.</li> <li>Concrete area outside to the west of the building features numerous concrete cuts and former material bays.</li> <li>Large open cut in concrete approximately 4 square metres in size is present on the western side (rear) concrete yard. Soft sands and gravels consistent with fill are present within the cut (<b>Plate 21</b>).</li> <li>No evidence of staining in concreted area or internally within building.</li> <li>Large sump of unknown use is present at rear of sign industry training area (western side of the building).</li> <li>Numerous sheds present at rear of building, sheds could not be accessed.</li> <li>Storage bays were present outside to the south of the building and are currently used to store machinery and various other materials and equipment.</li> </ul>	<b>Plate 16</b> <b>Plate 17</b> <b>Plate 18</b> <b>Plate 19</b> <b>Plate 20</b> <b>Plate 21</b>
Building 7 – Amenities Building	<ul style="list-style-type: none"> <li>South-east of Building 3</li> <li>Classroom facilities only</li> </ul>	
Building 10 – Distribution Centre	<ul style="list-style-type: none"> <li>South-west corner of site</li> <li>Distribution centre for various bulk materials.</li> <li>Concrete pad at rear of distribution centre.</li> <li>Metal barrier consistent with that used to house above ground storage tanks (AST) present in yard of distribution centre. However, no tanks or staining were observed during the site inspection.</li> <li>Small gas cylinder storage cage adjacent to Building 10.</li> </ul>	<b>Plate 22</b> <b>Plate 23</b> <b>Plate 24</b>
Building 11 – Hazardous chemical storage	<ul style="list-style-type: none"> <li>Hazardous chemical storage building consisting of separated eastern and northern rooms.</li> <li>Eastern side of storage empty.</li> <li>Western storage area contains small amounts of unspecified toxic chemicals and a large drum of white spirit.</li> <li>Strong ammonia odour within room.</li> <li>No staining evident.</li> </ul>	<b>Plate 25</b> <b>Plate 26</b>
Building 12 – Storage	<ul style="list-style-type: none"> <li>No access was available at the time of the site</li> </ul>	

Building	Description	Plates
Aquaculture	inspection.	
Building 13 – Farriery Workshop	<ul style="list-style-type: none"> <li>No access was available at the time of the site inspection.</li> </ul>	
Shed/Shelter 1 to 23	<ul style="list-style-type: none"> <li>Sheds/shelters predominantly located in the north-east and west of the site (except SH21, located east of Building 2)</li> <li>Typically galvanised iron or Colorbond construction and used for storage.</li> <li>SH16 was noted to be an aviary (located west of Building 4)</li> <li>SH4 and SH5 in the north of the site were noted to be garages</li> <li>A gas cylinder cage containing cylinders is present to the west of Shed 12.</li> <li>No access was available to agricultural sheds SH4, SH5, SH7, SH9 and SH23 at the time of the inspection.</li> </ul>	<b>Plate 27</b>

### 6.2.2 Drainage

A variety of surfaces cover the site including asphalt, bare ground, gravel, paving and landscaped areas (**refer to Plates**). Stormwater sumps were noted to be present across the site, which are directed to interior roads and offsite. Drainage was noted to be of concrete construction and no large earthen drains were identified on-site. There was noted to be no on-site collection of surface water.

### 6.2.3 Services

Multiple service pits and manhole covers were identified at the site which indicated that the site is connected to municipal water, sewer and gas.

Transformers are present on site to the west of Building 4 and adjacent north of Shed 16. The site is connected to main power by high voltage underground cable.

Fire hydrants are present across the site.

### 6.2.4 Aboveground and underground fuel storage

No evidence of aboveground storage tanks and/or underground storage tanks was identified during the site inspection. However concrete scarring, including concrete cuts and discolouration, was identified west of former spray-painting building (Building 4A).

### 6.2.5 Settlement Tanks

Historical plans identify two settlement tanks located on the southern side of Building 3 (Cafeteria). There was no observation or evidential signs of these settlement tanks during the site inspection,

## 6.3 Other Observations

The following additional observations were made at the site:

- Stockpiled soil (approximately 128m<sup>3</sup>) was noted in the south-west corner of the site (north-west of Building 10) (**Plate 28**). The stockpiled soil seems of mixed quality and is not consistent with virgin material.
- A kiln / pizza oven is present to the west of Building 4 (**Plate 29**).
- No asbestos warning stickers were noted at the site.

## 6.4 Personnel Interviews

During the site inspection two members of staff were asked questions when encountered across the site. Items that are worth noting are:

- The receptionist within the applied science building was not aware of any bulk chemical storage associated with the building; however she did state that small quantities of chemicals are used as part of various practices associated with the laboratories.
- Staff within the distribution centre who stated to have been present at the site for 10 years commented they were not aware of any bulk fuel storage, including underground storage tanks, being present on the site.

## 7.0 Site History

### 7.1 Past and Current Site Ownership and Occupancy

Past and current site ownership and occupancy details attained from the SAILIS online database<sup>13</sup> are summarised in **Table 7-1** and provided in **Appendix G**.

**Table 7-1 Past and Current Site Ownership and Occupancy**

Certificate of Title	Dealings and Date	Details	Parent Title(s)
Current title: CT 5519/164	transfer dealing completed 21/03/2017 (dealing number 12688838)	Urban Renewal Authority	CT4393/578
	vesting dealing completed 28/06/2012 (dealing number 11780158)	Minister for Employment, Higher Education and Skills	
	vesting dealing completed 19/12/2008 (dealing number 11055087)	Minister for Employment, Training and Further Education	
	title created through converted title dealing, title issued 30/03/1998 (converted to a computerised title)	Minister of Employment and Further Education	
Parent title: CT4393/578	original land grant issued 9/12/1991	Minister of Employment and Further Education	Unknown

### 7.2 Historical Aerial Photography Review

A review of aerial photography from 1949 to present is presented in **Table 7-2** and aerial photographs are provided in **Appendix H**.

In summary, no evidence of significant PCAs is apparent from the aerial photography. The site was vacant and utilised for small-scale agriculture (pastoral land) until 1979. In 1979 the TAFE appeared to be under construction. The TAFE buildings remain onsite in 2019 with some minor changes evident.

**Table 7-2 Historical Aerial Photography Review**

Date	Aerial Description
1949	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>The site is a part of a larger allotment with no defined boundaries.</li> <li>The site is clear and does not appear to be utilised for any purposes</li> </ul> <p><b>Surrounding</b></p> <ul style="list-style-type: none"> <li>North: Undeveloped Land</li> <li>East: Undeveloped Land, possible small-scale agriculture (pastoral land)</li> <li>South: Undeveloped land</li> <li>West: Undeveloped land.</li> </ul>
1959	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>The site remains undeveloped.</li> <li>Along the southern boundary covering approximately 20 percent of the site appears to be small-scale agriculture (pastoral land)</li> </ul> <p><b>Off-site</b></p> <ul style="list-style-type: none"> <li>North: No significant change</li> </ul>

<sup>13</sup> Land Services SA, 2019, South Australian Integrated Land Information System (SAILIS), Historical Search, viewed 23 April 2019, <https://www.sailis.sa.gov.au/>

Date	Aerial Description
	<ul style="list-style-type: none"> <li>East: A road has been developed, followed by possible pastoral land</li> <li>South: The land appears to be utilised for small-scale agriculture (pastoral land)</li> <li>West: The land is still vacant with some sections utilised for small-scale agriculture (pastoral land)</li> </ul>
1969	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>Although still vacant the site appears to be utilised for small-scale agriculture/pastoral land (cropping)</li> </ul> <p><b>Off-site</b></p> <ul style="list-style-type: none"> <li>North: Utilised for small-scale agriculture (pastoral land)</li> <li>East: There has been some development of residential dwellings on the eastern side of the adjacent road</li> <li>South: Utilised for small-scale agriculture (pastoral land)</li> <li>West: Utilised for small-scale agriculture (pastoral land)</li> </ul>
1979	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>The site has now been developed with defined boundaries</li> <li>Construction of the TAFE is in progress. It appears that the western building is almost complete, with the northern, eastern and southern building under construction</li> <li>Bitumen roads surrounding the TAFE are also under construction</li> <li>The construction headquarters appears to be located near the north east corner of the site (based on the presence of a number of small buildings and cars parked around these buildings).</li> </ul> <p><b>Off-Site</b></p> <ul style="list-style-type: none"> <li>North: Still vacant and possibly utilised for small-scale agriculture (grazing)</li> <li>East: No significant change</li> <li>South: There has been the development of a sporting oval and some buildings</li> <li>West: Adjacent and along the western boundary is stockpiled soil, and an unsealed road</li> </ul>
1989	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>The main TAFE has been completely constructed</li> <li>There are at least five buildings/structures located slightly east of the centre of the northern boundary and two within the north-east corner.</li> <li>Bitumen roads and carparking areas surround the TAFE buildings and unsealed portions are planted in grass and trees</li> </ul> <p><b>Off-Site</b></p> <ul style="list-style-type: none"> <li>North: No significant change</li> <li>East: No significant change</li> <li>South: No significant change</li> <li>West: A main bituminised road has been developed adjacent to the western boundary, followed by vacant land</li> </ul>
1999	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>The largest (and furthest west) of the buildings/structures located at the northern boundary in the 1989 imagery has been removed</li> <li>The trees at the site have grown significantly compared with the 1989 aerial photograph</li> <li>The grass has been cleared in the south western portion of the site</li> </ul> <p><b>Off-Site</b></p> <ul style="list-style-type: none"> <li>North: No significant change</li> <li>East: Residential housing to the south east has increased significantly</li> <li>South: No significant change</li> <li>West: There has been significant development of residential housing on the western side of the main road</li> </ul>

Date	Aerial Description
2005	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>• Minor changes to onsite buildings 4 and 4A are apparent</li> <li>• An additional bitumen carpark has been constructed north of Building 1</li> <li>• Shed 9 (galvanised iron store and hay shed) has replaced a smaller building/structure in the north-east of the site<sup>14</sup></li> <li>• The two unknown buildings/structures located in the north-east corner have been removed</li> </ul> <p><b>Off-site</b></p> <ul style="list-style-type: none"> <li>• North: No significant change</li> <li>• East: No significant change</li> <li>• South: No significant change</li> <li>• West: There has been the development of some new residential housing</li> </ul>
2009	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>• There has been the addition of building 10, with joining bitumen car park, in the south west corner. This building is noted to be the distribution centre on building plans last modified in February 2018.</li> <li>• There appears to be a small cleared section that is also utilised for some car parking in this area</li> </ul> <p><b>Off-Site</b></p> <ul style="list-style-type: none"> <li>• North: No significant change</li> <li>• East: No significant change</li> <li>• South: No significant change</li> <li>• West: No significant change</li> </ul>
2019	<p><b>On-Site</b></p> <ul style="list-style-type: none"> <li>• Bitumen carparks have been removed from the north western portion</li> <li>• Shed 23 (Colorbond hay shed) has been built in the north of the site</li> <li>• A building that appears to be Building 13 has been constructed west of building 4A and shed 12 (horse day yards)</li> </ul> <p><b>Off-Site</b></p> <ul style="list-style-type: none"> <li>• North: No significant change</li> <li>• East: No significant change</li> <li>• South: No significant change</li> <li>• West: No significant change</li> </ul>

<sup>14</sup> The building names used to describe the aerial imagery from 2005, 2009 and 2019 are based on the following site plan provided in **Appendix B**: Department of Planning, Transport and Infrastructure Government of South Australia, Drawing Title: TAFE SA Adelaide North Gilles Plains Campus, Blacks Road, Gilles Plains, 5086, created by J Sutton 1996, Modified by T Tan February 2018, Audited by A. Bryant July 2007, SAMIS no. 01503

## 7.3 Public Records

### 7.3.1 SA EPA Section 7 Public Register

Section 7 Statements (Land and Business Sale and Conveyancing Act 1994) for the current land parcel was requested from the Environmental Protection Authority (EPA). A copy of the document obtained is presented in **Appendix I**.

There were no conditions, enforcement notices, requirements, or orders under the selected sections of the following acts, recorded for the site in the SA EPA Section 7 Search:

- Environment Protection Act 1993 (SA);
- Land and Business (Sale and Conveyancing) Act 1994 (SA);
- South Australian Waste Management Commission Act 1979 (SA) (ceased);
- Waste Management Act 1987 (SA) (ceased); and
- South Australian Health Commission Act 1976 (ceased).

### 7.3.2 SA EPA Site Contamination Index

A search of the EPA site contamination index was undertaken on 19 April 2019 for the suburb of Gilles Plains<sup>15</sup>. A summary of records in proximity to the site is detailed in **Table 7-3**.

The index was last updated on 23 January 2019.

**Table 7-3: Site Contamination Index Results**

EPA Reference	Type	Address	PCA	Distance from site
61588	Audit Notification	Lot 51 Blacks Road GILLES PLAINS SA 5086	Agricultural activities	Adjacent Allotment to the North
61062	Audit Notification	846 & 848 Grand Junction Road GILLES PLAINS SA 5086	Service stations	800 m north-east
61588 - 001	Audit Report	Lot 51 Blacks Road GILLES PLAINS SA 5086	Agricultural activities	Adjacent Allotment to the North
12034	Pre 1 July 2009 Audit Notification	641 North East Road GILLES PLAINS SA 5086	Not recorded	500 m east
11616	Pre 1 July 2009 Audit Notification	643 North East Road GILLES PLAINS SA 5086	Not recorded	500 m east
12034 - 001	Pre 1 July 2009 Audit Report	641 North East Road GILLES PLAINS SA 5086	Not recorded	500 m east

<sup>15</sup> South Australian Environmental Protection Agency (SA EPA) Search Contamination Site Index, last modified 23 January 2019, viewed 18 April 2019, [www.epa.sa.gov.au/data\\_and\\_publications/site\\_contamination\\_index](http://www.epa.sa.gov.au/data_and_publications/site_contamination_index)

EPA Reference	Type	Address	PCA	Distance from site
11616	Pre 1 July 2009 Audit Termination	643 North East Road GILLES PLAINS SA 5086	Not recorded	500 m east
11940	S83 Notification	641 North East Road GILLES PLAINS SA 5086	Not recorded	500 m east
61042 - 01	S83A Notification	846 & 848 Grand Junction Road GILLES PLAINS SA 5086	Not recorded	800 m north-east
60598	SAHC	Pt Sec 872 & 874 Grand Junction Road GILLES PLAINS SA 5086	Not recorded	500 m north-east

### 7.3.3 EPA Authorisations (Licences) Index

A search of the EPA Authorisation records was undertaken on 18 April 2019 for the suburb of Gilles Plains. The following EPA authorisation records were listed for Gilles Plains<sup>16</sup>.

The index was last updated on 30 May 2018.

A summary of records in proximity of the site is detailed in **Table 7-4**.

**Table 7-4 EPA Authorisations (Licences) Index Results**

Document	Type	Name	Status	Published
37102	Licence	SOUTH AUSTRALIAN HEALTH AND MEDICAL RESEARCH INSTITUTE LIMITED	Issued	25/08/2017
2609	Licence	SA PATHOLOGY	Issued	11/04/2017
30082	Licence	POWER BRAKES (S.A.) PTY. LIMITED	Issued	11/04/2017

### 7.3.4 Environmental Protection and Clean Up Orders

A search of the Environment Protection and Clean Up Order records was undertaken on 11 April 2019 for the suburb of Gilles Plains. No EPA records were listed for Gilles Plains<sup>17</sup>.

The index was last updated on 30 May 2018.

### 7.3.5 Dangerous Substances Licence Search

A Dangerous Substances Licence search dated 20 March 2019 was provided by Renewal SA and is included as **Appendix J**.

The search did not identify any current or historical dangerous substance records for the site.

<sup>16</sup> South Australian Environmental Protection Agency (SA EPA) Search Authorisations, last modified 30 May 2018, viewed 18 April 2019, [www.epa.sa.gov.au/data\\_and\\_publications/environmental\\_authorisations\\_licences](http://www.epa.sa.gov.au/data_and_publications/environmental_authorisations_licences)

<sup>17</sup> South Australian Environmental Protection Agency (SA EPA) Search All Orders, last modified 30 May 2018, viewed 18 April 2019, [www.epa.sa.gov.au/data\\_and\\_publications/orders/search-all-orders](http://www.epa.sa.gov.au/data_and_publications/orders/search-all-orders)

## 7.4 Previous Environmental Reports

There are no known historical reports for the site.

AECOM requested and received an Audit report for the adjacent allotment located north of the site at Lot 51 Blacks Road. The investigation consisted of a site history, soil assessment and an attempt to drill to groundwater. The report focused on the potential contaminating activity of low scale agricultural use and asbestos containing materials. The investigation did not identify contaminants in the soil that precluded the site for potential residential use, however, surface asbestos contaminant material (ACM) was discovered and subsequently removed. Bulk soil tests for asbestos fines were conducted and did not identify any fibres within the soil. The site was signed off as suitable for residential use. This site is unlikely to cause any contamination to the subject site.

## 7.5 Asbestos Register

A Hazardous Materials Report which entailed an asbestos inspection report, recommended actions and register for the site was conducted by Asbestos Services in 2016, included as **Appendix D**<sup>18</sup>.

The locations of buildings discussed in the asbestos report are shown on the historical site plan saved in **Appendix B**<sup>19</sup>.

The register identified multiple non-friable ACMs across several buildings within the campus including Building 1, Building 2, Building 3, Building 4 and Building 4A. It was recommended that this asbestos be monitored and should be removed if damaged or during upgrades.

It was noted that Building 6, Shed 1, Shed 2, Shed 15, Shed 16, Shed 17, Shed 18, were not included in the survey/inspection.

Friable asbestos was detected and remained within the following:

- Boiler – North building 1, level 3, Gasket (firestop asbestos plaster), in good condition with the recommendation to use care during maintenance and replace if disturbed.

Friable asbestos was detected and removed from the following:

- Boilers – North building, level 3, located in the door gasket, textile cloth, gasket (sectional joins and castable pugging) and millboard, all friable asbestos subsequently removed.
- Appliances – East building 2, level 2, asbestos millboard, asbestos sheathed wiring, friable asbestos subsequently removed.
- Appliances – South building 4, level 1, asbestos rope subsequently removed.
- Laboratory Equipment – South building 4, level 1, asbestos millboard located in the labmaster oven as thermal insulation, subsequently removed.
- Laboratory Equipment – South building 4, level 1 – asbestos textile cloth used in heat proof mats, subsequently removed.
- Appliances – South building 4a, level 1 – asbestos rope within an oven door seal, subsequently removed.

The asbestos register has indicated that almost all of the friable asbestos has been removed from the site. The remaining non-friable ACMs currently onsite is considered low risk.

---

<sup>18</sup> Asbestos Services, 2016, Inspection Report, Recommended Actions and Register Only – Type: Asbestos, dated 26 September 2019.

<sup>19</sup> Department of Planning, Transport and Infrastructure Government of South Australia, Drawing Title: TAFE SA Adelaide North Gilles Plains Campus, Blacks Road, Gilles Plains, 5086, created by J Sutton 1996, Modified by T Tan February 2018, Audited by A. Bryant July 2007, SAMIS no. 01503.

## 8.0 Data Gaps

As per the ASC NEPM Schedule B2 (NEPC, 1999) significant data gaps should be identified when preparing a PSI.

Data gaps relevant to the achievement of the objectives of this PSI are summarised in **Table 8-1**

**Table 8-1: Data gaps**

Data gap	Significance
Long serving staff interviews	<p>No long serving current or former staff were identified to provide anecdotal information on historical practices at the site.</p> <p>Although this information would be useful it does not preclude the objectives of the PSI from being achieved.</p>
Former Spray Painting area and unknown use of sump at the rear of Building 4A	<p>There are no historical records of specific spray painting activities undertaken or disposal records of disused paints.</p> <p>In the absence of detailed use of the adjoining sump to Building 4A, it is unclear what it was used for.</p> <p>There is a possibility that chemicals associated with Building 4A (former spray painting and building studies) were disposed into the sump.</p>
Current status of the historical settlement tanks	<p>While historical records exist of two settlement tanks, there was no visual evidence during the site walkover that these still exist.</p> <p>There are no historical records of wastes which flowed into the tanks, however, it is assumed that this was solely waste from the cafeteria.</p> <p>In the absence of any removal records it is assumed that the settlement tanks still exist on site.</p>
<p>Detailed records or anecdotal evidence relating to historical practices associated with:</p> <ul style="list-style-type: none"> <li>• Application of pesticides and herbicides</li> <li>• Fill or soil importation</li> </ul>	<p>As no records could be identified relating to these items it is necessary to assume that the application of pesticides and herbicides may exist.</p> <p>Visual fill material was observed during the site inspection, it is unknown what the current classification of the fill material.</p>
Historical and current dental practices	<p>It is unknown what practices, including use and disposal of mercury amalgam, have historically and are currently undertaken in the dental studies and clinic rooms.</p> <p>However, due the age of the building and associated services it is most likely that any hard waste is disposed following industry dental practices and liquid waste disposed into the sites sewerage.</p>

## 9.0 Preliminary Conceptual Site Model

### 9.1 Elements of a conceptual site model

A preliminary conceptual site model (CSM) has been formulated utilising available information to determine the presence of potential exposure pathways and hence the presence of significant risk to susceptible receptors such as humans, ecosystems or the built environment. For a significant or identifiable risk to exist an exposure pathway must be present which requires each of the following to be identified:

- The presence of substances that may cause harm (SOURCE);
- The existence of means of exposing a receptor to the source (PATHWAY); and
- The presence of a receptor which may be harmed at an exposure point (RECEPTOR).

In the absence of a plausible exposure pathway there is no risk. Therefore, the presence of measurable concentrations of chemical substances resulting from previous site activities does not automatically imply that the impacts will cause harm. In order for this to be the case a plausible exposure pathway must be present allowing a source to adversely affect a receptor. The nature and importance of both receptors and exposure routes, which are relevant to any particular site, will vary according to its characteristics, intended end-use and its environmental setting.

### 9.2 Identified Potentially Contaminating Activities

Based on the site history investigation conducted by AECOM, the PCAs identified for the site are summarised in **Table 9-1** with the likelihood of each PCA to have occurred and the significance of any potential resultant contamination. The identified PCAs (with the exception of spray painting) at the site are not included in the PCAs defined in Part 1 of Schedule 3 of the Environment Protection Regulations 2009.

PCAs that are considered unlikely to have occurred or not of significance are deemed to not warrant further consideration.

The suspected location of each PCA is detailed on **Figure 2, Appendix B**.

Table 9-1: Potentially Contaminating Activities

PCA	COPCs	Description	Likelihood	Significance
Chemical Storage	<ul style="list-style-type: none"> <li>Total recoverable hydrocarbons (TRH)</li> <li>Benzene, toluene, ethylbenzene, xylenes, naphthalene (BTEXN)</li> <li>Polycyclic-aromatic hydrocarbons (PAHs)</li> <li>Volatile organic compounds (VOCs)</li> <li>Metals</li> </ul>	<p>A dedicated hazardous chemical storage (Building 11) was identified during the site inspection.</p> <p>A large drum of white spirit and small quantities of various (unlabelled) chemicals were present in one compartment of the store. A strong ammonia-like odour was noted in the room.</p> <p>No evidence of staining was observed.</p> <p>There is potential that larger quantities of other hazardous substances (including fuels and solvent) have historically been stored in the storage and as such the potential for contamination exists.</p> <p>However, given no evidence of staining was observed and the building is a dedicated storage facility and concrete sealed, wide spread impact is considered unlikely.</p>	Possible	Medium
Former Spray Painting area	<ul style="list-style-type: none"> <li>TRH</li> <li>BTEXN</li> <li>PAHs</li> <li>VOCs</li> </ul>	<p>Building 4A included the former sign industry training area which is understood to have included the use of paints and associated chemicals.</p> <p>Given no record of the specific activities undertaken as part of the training and disposal practices there is potential for contamination to have occurred associated with these activities.</p> <p>It is noted that no staining was noted in the building or in the rear concrete yard.</p>	Possible	Medium
Historical and current low scale agricultural use	<ul style="list-style-type: none"> <li>Organochlorine Pesticides (OCP)</li> <li>Organophosphorus Pesticides (OPP)</li> <li>Acid Herbicides</li> <li>Triazines</li> </ul>	<p>Historical aerial photographs indicate the site was utilised for pastoral land.</p> <p>Currently northern portions of the site are utilised for grazing land.</p>	Possible	Low

PCA	COPCs	Description	Likelihood	Significance
Settlement Tanks	<ul style="list-style-type: none"> <li>Oil and grease</li> <li>Nutrients</li> </ul>	<p>There are two known settlement tanks / grease traps located on the southern boundary of building 3.</p> <p>The settlement tanks are assumed to be associated with the cafeteria within the building, however it could not be ruled out that any other waste flows into these tanks.</p>	Unlikely	Low
Sump	<ul style="list-style-type: none"> <li>TRH</li> <li>BTEXN</li> <li>PAHs</li> <li>VOCS</li> <li>Metals</li> </ul>	<p>A large sump of unknown use was identified at the rear of Building 4a during the site walkover.</p> <p>The historical use for Building 4a has been identified as a spray painting area and building studies, however there is no information on the use of the sump. It is possible that, being located directly outside of the training areas, chemicals associated with former activities in Building 4a (paints and chemicals) have been potentially disposed in the sump.</p>	Possible	Low
Possible herbicide and pesticide use in the vicinity of current buildings	<ul style="list-style-type: none"> <li>OCPs</li> <li>OPPs</li> <li>Arsenic</li> </ul>	<p>There is the possibility of historical herbicide for weed control within garden beds and pesticides/termiticides applied to building footprints</p> <p>However, providing application was undertaken in accordance with manufacturer's instructions significant wide spread contamination is considered unlikely.</p>	Possible	Low
ACMs associated with onsite buildings, boilers and laboratory equipment.	<ul style="list-style-type: none"> <li>ACMs</li> </ul>	<p>ACMs are known to exist at a number of locations at the site.</p> <p>Providing these materials are monitored and managed as per the asbestos register for the site significant contamination from these materials is considered unlikely.</p>	Known to exist	Low
Fill or soil importation	<ul style="list-style-type: none"> <li>Metals</li> <li>OCPs / OPPs</li> <li>TRH</li> <li>BTEX</li> <li>PAH</li> <li>ACM</li> </ul>	<p>Fill and soil stockpile is located to the west of Building 10.</p> <p>The material observed was not consistent with virgin sand materials and seemed of variable quality.</p>	Likely	Low

### 9.3 Potential transport mechanisms and exposure routes

The main transport mechanisms and exposure routes that could be feasible for current and potential future use(s) of the site are:

- Via dermal contact by on-site workers and subsurface utility and demolition/excavation workers during any redevelopment.
- Surface water infiltration leading to downward leaching of contaminants within shallow soils.
- Airborne migration of soil particle leading to inhalation.
- Migration through groundwater.
- Dermal contact and ingestion of groundwater in the event of groundwater extraction.
- Inhalation via vapour intrusion.

### 9.4 Potential receptors

The following key site specific receptors are feasible:

- Future construction / maintenance workers at the site (during and post-development).
- Future occupants / users of the site.
- Residents to the north, east, south and west of the site.
- Recreational users to the north, east, south and west of the site.

### 9.5 Potential exposure pathways

On the basis of the available information gathered as part of the PSI, the preliminary CSM in terms of potential source-pathway-receptor linkages is provided in Table 8.2. Based on the site inspection, the site surface is sealed in areas of the majority of identifiable PCAs, therefore the direct contact exposure for current site users is mostly incomplete. If the site is redeveloped however, there is potential for exposure to future occupiers and /or construction and maintenance workers at the site.

Table 9-2 Potentially complete exposure pathways

PCA	Potentially Impacted Media	Pathway	Receptor	Comment
Chemical Storage Areas Former Spray Painting Area Sump Area	Soil	Dermal contact	Intrusive maintenance workers	Soil impacts (if any) are only relevant to intrusive works.
			Construction workers during development	Exposure risk likely managed through standard occupational, health and safety protocols.
		Incidental Ingestion	Intrusive maintenance workers	Soil impacts (if any) are only relevant to intrusive works.
			Construction workers during development	Exposure risk likely managed through standard occupational, health and safety protocols.
	Groundwater	Dermal contact and incidental ingestion.	Intrusive maintenance workers	Groundwater is expected to exist at depths greater than 5-10 m bgl. As such, any dermal exposure or incidental ingestion during intrusive works is not considered realistic.
			Construction workers during development	
			Off-site groundwater users	
		Ingestion	Off-site groundwater users	The nearest registered groundwater bore potentially for extractive purposes is located 410 m west-north-west from the site. This bore is an observational / recreational bore installed to 17 m depth in 1992, targeting the Hindmarsh

PCA	Potentially Impacted Media	Pathway	Receptor	Comment
				clay aquifer.
				There is potential for dermal contact and incidental ingestion of extracted groundwater associated with the potential use of groundwater for recreational purposes (e.g. filling of swimming pools).
				However given the significant distance of the bore from the site this exposure pathway is considered unlikely to exist.
	Intruding Vapours	Inhalation	Intrusive maintenance workers	Exposure risk is only relevant to works being undertaken in vicinity of chemical storage building.  Exposure risk likely managed through standard occupational, health and safety protocols.
			Current commercial workers	Exposure risk is unlikely based on limited exposure time to COPC under standard occupational, health and safety protocols.
			Future on-site residents	Exposure to intruding vapours within residential properties is relevant to properties that may be constructed within the

PCA	Potentially Impacted Media	Pathway	Receptor	Comment
				vicinity of the former spray painting area, sump area and chemical storage shed.
<p>Historical and current low scale agricultural use.</p> <p>Possible herbicide and pesticide use in the vicinity of onsite buildings</p> <p>Fill or soil importation</p>	Soil	Dermal contact and incidental ingestion.	Commercial Workers	Dermal contact and incidental exposure with impacted soils at the site for current occupants is possible. However, exposure is considered limited given limited given works are largely office based, with the exception of those undertaking maintenance of site grounds.
			Intrusive maintenance workers	Exposure risk likely managed through standard occupational, health and safety protocols.
			On-site residents	If low density housing constructed exposure to impacted surface soils is possible.
			Construction workers during development	Exposure risk likely managed through standard occupational, health and safety protocols.
		Inhalation of dust	Construction workers during development	During development the generation of significant amounts of impacted dust is possible.
			Residential properties to the east, south and west of property	

PCA	Potentially Impacted Media	Pathway	Receptor	Comment
			Recreational ground users to the north	It is expected that this exposure would be managed through appropriate dust management strategies during development.
			Occupants of the school to the west	
Settlement Tanks	Soil	Dermal contact and incidental ingestion.	Intrusive maintenance workers	Exposure risk is possible, however is considered unlikely when waste from the tanks is managed and disposed through standard occupational, health and safety protocols.
			Commercial Workers	Dermal contact and incidental exposure with impacted soils at the site for current occupants is unlikely, particularly given the tanks are most likely located underground.
			Future onsite-residents	Potential for any dermal contact or incidental ingestion would be unlikely if settlement tanks and any surrounding impacted soil were removed during demolition works.
ACMs associated with onsite buildings, boilers and laboratory equipment	Air	Inhalation of asbestos fibres	Construction workers during development	During demolition the generation of friable asbestos fibres is possible.  Potential exposure would be managed through appropriate management

PCA	Potentially Impacted Media	Pathway	Receptor	Comment
				strategies during demolition works and any ACMs would be removed from the site.
			Future on-site residents	Potential exposure would be eliminated to future on-site residents if all existing ACM is appropriately managed and removed from site during demolition works.

## 10.0 Conclusion

Based on the identified PCAs, it is unlikely any unacceptable risk to human health exists based on the site's current commercial use, providing that any intrusive or maintenance works are undertaken in accordance with standard occupational health and safety protocols.

If the site use is potentially to be changed to low density residential, and assuming the settlement tanks and identified ACMs are removed in accordance with industry standards, further investigations are warranted to assess risk to human health associated with the following identified PCAs:

- Chemical Storage;
- Former spray painting area;
- Historical and current low scale agriculture;
- Possible herbicide and pesticide use in the vicinity of on-site buildings;
- Fill or soil importation; and
- Sump area.

It is noted that the identified PCAs (with the exception of spray painting) at the site are not included in the PCAs defined in Part 1 of Schedule 3 of the Environment Protection Regulations 2009. The identified PCAs are considered as having a low significance or highly localised and are unlikely to preclude the intended future land use.

## 11.0 References

**DWLBC (2006)** Overview of the Hydrogeology of the Adelaide Metropolitan Area, Department of Water, Land and Biodiversity Conservation, Report 2006/10.

**DEWNR (2019a)** Department of Environment, Water and Natural Resources, Nature Maps, <https://data.environment.sa.gov.au/NatureMaps/Pages/default.aspx>

**DEWNR (2019b)** Department of Environment, Water and Natural Resources, Groundwater Data Online Database, Government of South Australia, searched 28 August 2018, <https://www.waterconnect.sa.gov.au/GD>.

**DEWNR (2019c)** Department of Environment, Water and Natural Resources, Mapland

**DEW (2009)** Department of Environment and Water, Soil Association Map of the Adelaide Region

**Department of State Development, Resources and Energy (2012)** 1:100,000 Geological Survey of South Australia

**DPTI (2019)** Department of Transport and Infrastructure, Land Services Group historical title search, <https://www.sa.gov.au/topics/planning-and-property/land-services>

**FYFE (2016)** Site Contamination Audit Report – Allotment 51 Blacks Road, Gilles Plains, South Australia (EPA REF: 61588, 05/23060), 15 July 1026

**Nearmap (2009 and 2019)** Aerial imagery, <https://www.nearmap.com.au/>

**NEPC (1999)** *National Environmental Protection (Assessment of Site Contamination) Measure 1999*, as amended in 2013, National Environment Protection Council

**SA EPA (2009)** Environment Protection Regulations – Version 1 July 2018

**SA EPA (2019)** Section 7 Search

**SA EPA (2019a)** Site contamination Index search, accessed 11 April 2019, <https://www.epa.sa.gov.au/>

**SA EPA (2019b)** EPA Authorisation Index search, accessed 11 April 2019, <https://www.epa.sa.gov.au/>

**SA EPA (2019c)** EPA Site Contamination Assessment Order and Clean Up Order Index search, accessed 11 April 2019, <https://www.epa.sa.gov.au/>

**SA EPP (2015)** South Australian Environment Protection (Water Quality) Policy 2015 under the Environment Protection Act 1993. Government of South Australia.

**Safework SA (2019)** Dangerous substances search, <https://www.safework.sa.gov.au>

## 12.0 Limitations

These conclusions and all information in this Report is provided strictly in accordance with and subject to the following limitations and recommendations:


- a. The conclusions and all information in this Report are given strictly in accordance with and subject to the following limitations: This Report has been prepared with the usual care and thoroughness of the consulting profession for the use of the Crown and the SA Government (including Renewal SA) and/or the site contamination auditor and only those third parties who have been authorised in writing by AECOM to rely on this Report.
- b. This Report should be read in full. This agreement shall not create any rights or benefits to parties other than to the Crown and the South Australian Government (including Renewal SA) and the Service Provider to the extent permitted by law. Unless the Service Provider's prior written permission has been obtained no party other than the South Australian Government (including Renewal SA and/or the site contamination auditor) shall have the right to rely on the Service Provider's documents or opinions rendered in connection with the services This Report does not purport to give legal advice. Legal advice can only be given by qualified legal practitioners.
- c. This Report should be read in full and no excerpts are to be taken as representative of the findings. No responsibility is accepted by AECOM for use of any part of this Report in any other context.
- d. This conclusion is based solely on the information and findings contained in this Report.
- e. This conclusion is based solely on the scope of work agreed between AECOM and Renewal SA and described in Section 1.4 ("Scope of Work") of this Report.
- f. This Report is dated 23 April 2019 and is based on the conditions encountered during the site investigations conducted, and information reviewed, from 8 April 2019 to 23 April 2019. AECOM accepts no responsibility for any events arising from any changes in site conditions or in the information reviewed that have occurred after the completion of the site investigations.
- g. The investigations carried out for the purposes of the Report have been undertaken, and the Report has been prepared, in accordance with normal prudent practice and by reference to applicable environmental regulatory authority and industry standards, guidelines and assessment criteria in existence at the date of this Report.
- h. Where this Report indicates that information has been provided to AECOM by third parties, AECOM has made no independent verification of this information except as expressly stated in the Report. AECOM assumes no liability for any inaccuracies in or omissions to that information.
- i. AECOM has tested only for those chemicals specifically referred to in this Report. AECOM makes no statement or representation as to the existence (or otherwise) of any other chemicals.
- j. Except as otherwise specifically stated in this Report, AECOM makes no warranty or representation as to the presence or otherwise of asbestos and/or asbestos containing materials ("ACM") on the site. If fill has been imported on to the site at any time, or if any buildings constructed prior to 1970 have been demolished on the site or materials from such buildings disposed of on the site, the site may contain asbestos or ACM. Without limiting the generality of sub-clauses (h) and (m), even if asbestos was tested for and those test results did not reveal the presence of asbestos at specific points of sampling, asbestos may still be present at the site if fill has been imported at any time, or if any buildings constructed prior to 1970 have been demolished on the site or materials from such buildings disposed of on the site.
- k. No investigations have been undertaken into any off-site conditions, or whether any adjoining sites may have been impacted by contamination or other conditions originating from this site.
- l. Investigations undertaken in respect of this Report are constrained by the particular site conditions, such as the location of buildings, services and vegetation. As a result, not all relevant site features and contamination may have been identified in this Report.
- m. Subsurface conditions can vary across a particular site and cannot be exhaustively defined by the investigations described in this Report. It is unlikely therefore that the results and estimations

expressed in this Report will represent conditions at any location removed from the specific points of sampling.

- n. A site which appears to be unaffected by contamination at the time the Report was prepared may later, due to natural phenomena or human intervention, become contaminated.
- o. Except as specifically stated above, AECOM makes no warranty, statement or representation of any kind concerning the suitability of the site for any purpose or the permissibility of any use, development or re-development of the site.
- p. Use, development or re-development of the site for any purpose may require planning and other approvals and, in some cases, environmental regulatory authority approval. AECOM offers no opinion as to whether the current use has any or all approvals required, is operating in accordance with any approvals, the likelihood of obtaining any approvals for development or redevelopment of the site, or the conditions and obligations which such approvals may impose, which may include the requirement for additional environmental works.
- q. AECOM makes no determination or recommendation regarding a decision to provide or not to provide financing with respect to the site.
- r. The ongoing use of the site and/or the use of the site for any different purpose may require the owner/user to manage and/or remediate site conditions, such as contamination and other conditions, including but not limited to conditions referred to in this Report.
- s. To the extent permitted by law, AECOM expressly disclaims and excludes liability for any loss, damage, cost or expenses suffered by any third party relating to or resulting from the use of, or reliance on, any information contained in this Report. AECOM does not admit that any action, liability or claim may exist or be available to any third party.
- t. Except as specifically stated in this section, AECOM does not authorise the use of this Report by any third party.
- u. It is the responsibility of third parties to independently make inquiries or seek advice in relation to their particular requirements and proposed use of the site.

# Appendix A

## Figures



\\naud11p001\AECOM\_Projects\606\160603737\900\_CAD\_GIS\920\_GIS\FIGURES\MXD\60603737-Fig1.mxd Date Saved: 17/04/2019


# AECOM



1:5,000 (when printed at A3)

### Legend

- Site Boundary
- Highway
- Major Road
- Minor Roads




**Figure 1**  
**SITE LOCATION PLAN**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.  
- Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community  
Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only



**AECOM**



1:1,500 (when printed at A3)

**Legend**

Site Boundary

**PCAs**

- ① Historic Low Scale Agriculture (across site)
- ② Current Agricultural Land
- ③ Chemical Storage
- ④ Imported Fill (beneath buildings and car parks)
- ⑤ Settlement Tanks
- ⑥ ACM present in buildings
- ⑦ Possible Pesticide use
- ⑧ Sump Area
- ⑨ Former Spray Painting Area

Existing Settlement Tank

Agricultural Land

Building

**Figure 2:  
SITE FEATURES PLAN**

GILLES PLAINS TAFE


**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.

# Appendix B

## Historical Building Plans



BUILDINGS

- 1

ADMIN., RESOURCE & GENERAL TEACHING
- 2

PARA DENTAL STUDIES
- 3

THEATRE & CAFETERIA
- 4

VETERINARY & APPLIED SCIENCE
- 4A

BUILDING STUDIES
- 7

STUDENT AMENTITIES
- 10

DISTRIBUTION CENTRE
- 11

FLAMMABLE LIQUIDS STORE
- 12

STORAGE AQUACULTURE
- 13

FARRIERY WORKSHOP
- SH1

COLORBOND STORE SHED
- SH2

COLORBOND STORE SHED
- SH4

GALV. IRON GARAGE
- SH5

GALV. IRON GARAGE
- SH6

COLORBOND STORE SHED

PAVING DETAILS: Location, Type, Fail year, Area (sq ms)

B	bit-veh	2012	4055	C	bit-veh	2008	487
D	bit-veh	2012	428	E	bit-veh	2012	1679
F	bit-veh	2012	274	G	bit-veh	2012	494
H	bit-veh	2012	1041	I	bit-veh	2012	442
J	bit-veh	2012	1347	K	bit-veh	2021	439
L	bit-veh	2021	142	M	bit-veh	2012	1064
N	bit-veh	2012	1149	O	bit-veh	2008	448
P	bit-veh	2008	375	Q	bit-veh	2032	313
R	bit-veh	2032	285	S	bit-veh	2008	76
T	bit-veh	2008	599	U	bit-veh	2025	1386

FENCES \* code-height-type-fail date-length (ms) \*

CI	corrugated iron	PW	post and wire
CM	chain mesh	WM	weld mesh
GT	galtube	NF	not fenced
PG	pedestrian gate	VG	vehicle gate

\* Fence junction

TAFE SA ADELAIDE NORTH  
GILLES PLAINS CAMPUS  
BLACKS ROAD  
GILLES PLAINS 5086



Government of South Australia  
Department of Planning,  
Transport and Infrastructure

Asset no.	01503	Client.	DFEEST
DPTI Office.	ADELAIDE	Sheet.	1 of 1
Created by.	Archink	J Sutton	May 1996
Modified by.	Helica Archi	T Tan	Feb 2018
Audited by.	ARCHINK	A.Bryant	July 2007
Title details.	refer layer " site-allotment " C.T. 4393/578V		
Site area.	10.0864 ha	Accuracy.	Site Survey

Strategic Asset Management Information System Plan

SAMIS 01503

BUILDINGS (CONT)

- SH8

GALV. IRON SHED
- SH9

GALV. IRON STORE & HAY SHED
- SH10

COLORBOND SHELTER
- SH12

GALV. IRON TIMBER STORE/HOLDING BAY
- SH16

COLORBOND SHED - AVIARY
- SH19


GALV. IRON SHELTER
- SH20


GALV. IRON SHELTER
- SH21

GALV. IRON PLANT SHED
- SH22

TIMBER GAZEBO
- SH23

COLORBOND HAY SHED





CONSTRUCT NEW COVER TO EXIST. MANHOLE TYPE ML1 COVER EL 114-760 IL 113-632

DP N°	FINISHED TOP LEVEL	PIPE INVERT LEVEL
N19	116-140	114-670
E6	115-300	114-820
E7	114-820	113-995
E8	114-820	113-995
E9	114-820	113-995
E10	114-820	113-995
E11	114-820	113-995
E12	114-820	114-070
E13	114-820	114-070
E14	116-040	114-000
E15	116-000	114-000
E16	116-570	114-670
S1	114-370	115-620
S2	114-370	113-620
S3	114-870	114-000
S4	115-970	114-220
S5	115-400	114-220
S6	115-530	114-220
S7	114-950	113-820
S8	114-920	113-820
S9	114-370	113-670
S10	114-370	113-620
S11	114-925	113-620
S12	114-500	112-593
S13	114-370	113-620

- LIGHTING POLE LEGEND** NOT THIS CONTRACT
- 6 OF POLE 800mm FROM KERB
  - ★ POLE MOUNTED ADJACENT TO PATH
  - ✱ NOMINAL LOCATION OF SIGN FLOODLIGHT
  - ✱ POLE LOCATED AS INDICATED

- NOTES**
- STAGE 2 CONTRACT VARIATION
  - 2 DENOTES WORK IN THIS CONTRACT (STAGE 3)
  - EXTENT OF WORK THIS CONTRACT INCLUDES:  
(a) ADJUSTMENT OF EXISTING MANHOLES AND GULLIES AND CONSTRUCTION OF CONCRETE MANHOLE COVERS TO MANHOLES IN TEMPORARY HARDSTAND AREAS. SLOPE COVERS AND GRATES TO MATCH SURROUNDING GRADE.  
(b) SUB-SOIL DRAIN IN COURTYARD PLANTING AREAS, SUB-SOIL DRAIN FROM TREE TUBS AND SUB-SOIL DRAIN IN BARBEQUE GARDEN.
  - FOR T.B.M. REFER TO SHEET CF1

- F — EXIST FIRE SERVICE
- W — EXIST WATER SERVICE
- G — EXIST GAS SERVICE
- T — EXIST. TELECOM SERVICE
- EXIST. STORMWATER M.H.
- EXIST. SEWER MANHOLE
- NEW GULLY - CO-ORDINATES APPLY TO CENTRE
- NEW S.E.P. - CO-ORDINATES APPLY TO CENTRE ON FACE OF KERB
- NEW STORMWATER M.H. COVER
- NEW SUB-SOIL DRAIN
- EXIST HOSEBOX
- EXIST FIRE HYDRANT
- SUB-SOIL DRAIN CLEANOUT
- TREE TUB SEE DETAIL SHEET CF11
- OR EW MANHOLE PAVEMENT MARKER SEE SHEET CF10

C Top levels on DPs 37 & 58 13-72  
DP gully top levels 28-6  
E14, E16, 34, 55, 56  
A DP 53 moved 1250 south 20-67

Letter	REVISIONS	Date	Chkd	Appd

ASSOCIATED DOCUMENTS				
Arch	DP3	12-72		
Civil	28-6	13-72	Design	
Elect			Drawn	
Mech			Chkd	
Struct	28-6	13-72	Design	

Setting out of work is the responsibility of the contractor. All dimensions to be taken from the job. Discrepancies to be reported immediately to the Director. This drawing shall be read in conjunction with the specification.

Contractor <i>P.A. Duff</i>	Branch Head
Date 5/11/79	Date
Witness OK	Section Head
Date	Date

**John Connell & Associates Pty Ltd**  
CONSULTING ENGINEERS  
168 MELBOURNE ST, NORTH ADELAIDE, 5006  
TEL. 267 3111

**GILLES PLAINS COMMUNITY COLLEGE**

**Stage 3 Civil**

**UNDERGROUND SERVICES SHEET 2**


**SOUTH AUSTRALIAN GOVERNMENT PUBLIC BUILDINGS DEPARTMENT**  
Specification Number  
Scale 1:200  
Sheets in set CFB of 11

**705 SD 79**

# Appendix C

## Site Photographs

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 1.			
<b>Description:</b> Site eastern boundary.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 2.			
<b>Description:</b> Typical example of road circulating the main buildings on site.			


<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 3.			
<b>Description:</b> Site northern car park.			



<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 4.			
<b>Description:</b> Site northern car park.			



<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 5.	<div>☉ 306°NW (T)    ● 34°51'2"S, 138°39'7"E ±6m</div>  <div>AECOM 201912 Apr 2019, 11:21:59</div>		
<b>Description:</b> Northern agricultural pens used to house sheep and horses.  Adjacent residential properties to the north visible in the background.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 6.	<div>☼ 233°SW (T)    ● 34°51'4"S, 138°39'3"E ±6m</div>  <div>AECOM 201912 Apr 2019, 11:23:59</div>		
<b>Description:</b> Site north-west corner to right hand side of photo.  Agricultural pens extending around along site western boundary.			

<b>Site Name:</b> Gilles Plains TAFE	<b>Site Location:</b> Blacks Road, Gilles Plains
<b>Plate No.</b> 7.	<div data-bbox="488 331 1453 1048"> <div> <span>☼ 4°N (T)</span> <span>● 34°51'9"S, 138°39'13"E ±6m</span> </div>  <div> <span>AECOM 2019</span> <span>12 Apr 2019, 11:14:57</span> </div> </div>
<b>Description:</b> Grassed area present in east of site.	


<b>Site Name:</b> Gilles Plains TAFE	<b>Site Location:</b> Blacks Road, Gilles Plains
<b>Plate No.</b> 8.	<div data-bbox="488 1220 1453 1937"> <div> <span>☼ 250°W (T)</span> <span>● 34°51'10"S, 138°39'6"E ±6m</span> </div>  <div> <span>AECOM 2019</span> <span>12 Apr 2019, 11:34:49</span> </div> </div>
<b>Description:</b> Site south-west corner to which the site slopes.  Penned area is used as exercise area for dogs.  Stockpiled bark chips and mulch in photo foreground.	

<b>Site Name:</b> Gilles Plains TAFE	<b>Site Location:</b> Blacks Road, Gilles Plains
<b>Plate No.</b> 9.	<div data-bbox="491 331 1453 371">           266°W (T) 34°51'10"S, 138°39'12"E ±8m         </div>  <div data-bbox="491 1016 1453 1048">           AECOM 2019 12 Apr 2019, 11:06:40         </div>
<b>Description:</b> Site southern boundary with adjacent Disability SA visible.	

<b>Site Name:</b> Gilles Plains TAFE	<b>Site Location:</b> Blacks Road, Gilles Plains
<b>Plate No.</b> 10.	<div data-bbox="491 1218 1453 1258">           187°S (T) 34°51'4"S, 138°39'9"E ±6m         </div>  <div data-bbox="491 1901 1453 1933">           AECOM 2019 12 Apr 2019, 11:42:04         </div>
<b>Description:</b> Child care facility.	



<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 13.		 <p>⊗ 33°NE (T)   ● 34°51'7"S, 138°39'5"E ±128m</p> <p>AECOM 2019 12 Apr 2019, 12:28:44</p>	
<b>Description:</b> Maintenance room including some chemical storage located within Building 4.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 14.	<div><div>⊗ 357°N (T)   ● 34°51'7"S, 138°39'5"E ±32m</div></div>		
<b>Description:</b> Cylinder store connected to Building 4.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 15.		 <p>⊗ 289°W (T)   ● 34°51'5"S, 138°39'6"E ±48m</p> <p>AECOM 2019 <span style="float: right;">12 Apr 2019, 12:11:34</span></p>	
<b>Description:</b> Interior former bricklaying, tiling and plastering workshop within Building 4A.			


<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 16.		 <p>⊗ 83°E (T)   ● 34°51'6"S, 138°39'5"E ±48m</p> <p>AECOM 2019 <span style="float: right;">12 Apr 2019, 12:25:54</span></p>	
<b>Description:</b> Aquaculture within former workshop building within Building 4A.			





<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 19.		 <p>☼ 191°S (T)    ● 34°51'5"S, 138°39'3"E ±8m</p> <p>AECOM 2019 12 Apr 2019: 12:16:37</p>	
<b>Description:</b> Large sump of unknown use at rear of sign industry training area.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 20.			
<b>Description:</b> Rear area of sign industry training area and bricklaying, tiling and plastering workshop.  Numerous cuts in concrete.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 21.		<div><div>☼ 175°S (T)    ● 34°51'5"S, 138°39'3"E ±6m</div></div>	
<b>Description:</b> Large concrete cut at rear area of sign industry training area and bricklaying, tiling and plastering workshop.  Soils soft and sandy and consistent with fill.			


<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 22.	<div><div>☼ 305°NW (T)    ● 34°51'10"S, 138°39'3"E ±6m</div><div>AECOM 2019<span>12 Apr 2019, 11:29:34</span></div></div>		
<b>Description:</b> Cages and metal barrier within fenced area of Building 10.			


<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 23.	<div><div>☼ 130°SE (T)    ● 34°51'9"S, 138°39'4"E ±4m</div><div>AECOM 201912 Apr 2019, 11:29:03</div></div>		
<b>Description:</b> Gas cylinder storage outside of Building 10.			


<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 24.	<div><div>☼ 158°SE (T)    ● 34°51'9"S, 138°39'5"E ±12m</div><div>AECOM 201912 Apr 2019, 11:32:44</div></div>		
<b>Description:</b> Inside Building 10 distribution centre.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 25.			
<b>Description:</b> Hazardous chemical storage building in the left of photo.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 26.			
<b>Description:</b> Hazardous chemical store.			

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 27.		92°E (T) 34°51'6"S, 138°39'2"E ±6m	
<b>Description:</b> Gas cylinders located at the rear of shed 12 to the left.		 <p>AECOM 2019 12 Apr 2019, 11:25:26</p>	

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains	
<b>Plate No.</b> 28.		168°S (T) 34°51'7"S, 138°39'2"E ±8m	
<b>Description:</b> Stockpiled material to the north west of Building 10.		 <p>AECOM 2019 12 Apr 2019, 11:26:43</p>	

<b>Site Name:</b> Gilles Plains TAFE		<b>Site Location:</b> Blacks Road, Gilles Plains
<b>Plate No.</b> 29.	<div><div><div>☼ 307°NW (T)    ● 34°51'7"S, 138°39'4"E ±6m</div><div>AECOM 2019<span>12 Apr 2019, 11:51:26</span></div></div></div>	
<b>Description:</b> Kiln / pizza oven located to the west of bulding 4.		

# Appendix D

## Asbestos Reports

**INSPECTION REPORT, RECOMMENDED ACTIONS  
AND REGISTER ONLY**

**TYPE: ASBESTOS**

for

**Gilles Plains TAFE (F)  
Gilles Plains Campus  
LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

Printed on: 26/09/2016

**ASBESTOS SERVICES  
Ph: (08) 8226 4943**

**NOTE: Building and room numbers referred to in this report are as per the asset drawings and may not correspond to identification of buildings and room numbers on site. This asbestos register should be read in conjunction with the SAMIS site and floor plans.**

## INTRODUCTION

This document is a report on the survey/inspection of GILLES PLAINS CAMPUS for DFEEST for asbestos containing products in compliance with the Work Health and Safety Regulations, 2012 (SA).

Included in the report is a register of asbestos containing products identified as a result of the survey/inspection. It is a requirement of the Work Health and Safety Regulations, 2012, Chapter 8, Part 3 that a person with management or control of a workplace must ensure that an asbestos register is prepared, maintained and reviewed as necessary to ensure information is up to date and a copy is kept in the workplace. The regulations require regular inspections of the asbestos by a competent person.

Included in this report are Recommended Actions, the actions are recommendations only and the implementation is the responsibility of the building owner.

Building and room numbers referred to in this report are as per the asset drawings and may not correspond to identification of buildings and room numbers on site.

The Survey/Inspection was carried out by Pye for Asbestos Services on 25/08/2016.

## LIMITATIONS

The inspection was carried out in areas where access was available. Where inspection would involve demolition of walling, coatings, plant etc only limited inspection was made. Unless otherwise indicated, floor coverings were not taken up to enable inspection of floor surfaces. Equipment in use was not disturbed or opened for the purpose of inspection.

It should be noted that no inspection can be regarded as absolute and that demolition of structures may reveal incidences of asbestos products in situ which were not discovered during initial inspection.

Measurements/quantities mentioned in this report are approximate only.

These documents should not be used as contractual documents.

## REFERRED DOCUMENTS

It is recommended that the following documents be read in conjunction with this report.

Documents are available from the following websites:

[SafeWork SA](http://www.safework.sa.gov.au) (www.safework.sa.gov.au)

- Work Health and Safety Regulations, 2012 (SA), Chapter 8

[Safe Work Australia](http://www.safeworkaustralia.gov.au) (www.safeworkaustralia.gov.au)

- How to Safely Remove Asbestos Code of Practice (SafeWork Australia, December 2011).
  - How to Manage and Control Asbestos in the Workplace Code of Practice (SafeWork Australia, December 2011).
-

TYPE: **ASBESTOS**

LOCATION OF HAZARDOUS MATERIAL FOUND: **Gilles Plains Campus**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

ASSET: **Gilles Plains Campus**

This site was not included in the survey/inspection.

ELEMENT TYPE: **Not Identified**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is on the three sided sign posts

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

ASSET: **Gilles Plains Campus > Building 01**

ELEMENT TYPE: **Verandah**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 15 (square metres)  
USE: Ceiling Panels  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Generally Inaccessible

Verandah ceiling linings north elevation external to room 55

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

ASSET: **Gilles Plains Campus > Building 01**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 25 (square metres)  
USE: Eaves Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

The material is throughout the site as infill panels to window recesses

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01**

ELEMENT TYPE: **Building Exterior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 3 (square metres)  
USE: Refer To Memo  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Generally Inaccessible

Asbestos sheet Infill panel below sub floor level, 4 course clay brick wall in front external to north elevation room 56

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01**

ELEMENT TYPE: **External Walls**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

garden walls and soil retaining in planter boxes not generally visible. Replaced with non asbestos sheet.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 1100 (square metres)  
USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Ceiling linings to balcony walkways and main stairway

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01**

ELEMENT TYPE: **Footings / Stumps**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Poor Condition  
ACCESSIBILITY: Is Accessible

This is the formwork to retain the soil/pavement away from the pier and beam footing system. Planter boxes and lost formwork on north elevation have been removed. There may be more asbestos lost formwork that is not accessible.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01**

ELEMENT TYPE: **Air Conditioning Duct**  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Air Conditioning Duct Gasket  
FINISH TYPE: Natural  
FRIABILITY: Not Identified  
CONDITION: Is In Unknown Condition  
ACCESSIBILITY: Has No Access For Observation

Mastic sealant to original aircon duct flange joints have tested positive for asbestos take caution if working upon

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 1 > Room 033**

ELEMENT TYPE: **Ceiling**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 4 (square metres)  
USE: Ceiling Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

This is infills between top of the wall & the 1st floor slab honey coomb

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 1 > Room 035**

ELEMENT TYPE: **Switchboards**  
MATERIAL TYPE: Zelemite  
QUANTITY: Not Identified (<0.5 square metres)  
USE: Switchboard Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

500 x 500mm east wall

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 1 > Room 041**

ELEMENT TYPE: **Hot Water Service**  
MATERIAL TYPE: Asbestos Cement Pipe  
QUANTITY: 6 (metres)  
USE: Flue  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

There is two heaters

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 1 > Room 056**

ELEMENT TYPE: **Building Exterior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Formwork  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Generally Inaccessible

Refer to building exterior lost formwork/infill panel

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 1 > Room 060**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Female toilet - partitions.

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 1 > Room 061**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Male toilet - partitions.

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 2 > Room 202**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 2 > Room 203**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning

FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 2 > Room 229**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 2 > Room 231**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 301**

ELEMENT TYPE: Hot Water Service  
MATERIAL TYPE: Asbestos Cement Pipe  
QUANTITY: 3 (metres)  
USE: Flue  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Removed By Licensed Contractor

DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: Hot Water Service  
MATERIAL TYPE: Asbestos Cement Pipe  
QUANTITY: 9 (metres)  
USE: Flue  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Room 301 north elevation redundant flue from roof 2014

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: Furniture  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 1 (square metres)  
USE: Bench Tops  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Part of benchtop is broken ;remove as soon is practicable ++ not located 2005 inspection

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: Boiler  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Boiler Door Gasket  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Poor Condition  
ACCESSIBILITY: Has Limited Access

2 off boilers. Boiler access hatch seals to front & back of boiler. Refert to CEBM analysis 45020 dated 18 March 2014.  
Removed and replaced with non asbestos gaskets.

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Boiler**  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Boiler Door Gasket  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

CATEGORY: 5

RECOMMENDED ACTION: Use care during maintenance, replace if disturbed

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Boiler**  
MATERIAL TYPE: Asbestos Textile Cloth  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

This is on the flue box

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Room Interior**  
MATERIAL TYPE: Asbestos Fibre Gasket  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is stored in the maintenance locker

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Air Conditioning Duct**

MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Flexible Joints In Air Condit Ducts  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Mastic sealant to original airconditioning duct flange joints and registers may contain asbestos arrange asbestos analysis before working upon

CATEGORY: 3  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Boiler**  
MATERIAL TYPE: Castable Asbestos  
QUANTITY: Not Identified  
USE: Gasket  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Poor Condition  
ACCESSIBILITY: Has Limited Access

Asbestos plaster pugging and asbestos rope seals to top of sectionial joins in boiler. Refer to CEBM analysis 45017 dated 18 march 2014. Note asbestos material is still present between main cast sections of boiler.

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Boiler**  
MATERIAL TYPE: Castable Asbestos  
QUANTITY: Not Identified  
USE: Gasket  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Poor Condition  
ACCESSIBILITY: Is Accessible

2 off boilers. Boiler to flue castable pugging and asbestos rope seals. Refer to CEBM analysis 45018 dated 18 March 2014.

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: **Boiler**  
MATERIAL TYPE: Asbestos Millboard

QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

Non asbestos Front burner to boiler gasket, refer to CEBM analysis 45016 dated 18 March 2014.

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: Room Interior  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is stored in this room on top of a wooden crate

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: Boiler  
MATERIAL TYPE: Firestop Asbestos Plaster  
QUANTITY: Not Identified  
USE: Gasket  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

2 off boilers. Boiler metal cast section seals, refer to CEBM analysis 45019 dated 18 March 2014.

CATEGORY: 3  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 01 > Level 3 > Room 302**

ELEMENT TYPE: Room Interior  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: Not Identified  
USE: Gasket  
FINISH TYPE: Not Identified

FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

These gaskets are stored in this room in a wooden crate

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE: 01/02/2006

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: **Ceiling**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 90 (square metres)  
USE: Ceiling Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

This is the verandah lining in room 25. Informed by security asbestos removed in 2008. HSE 25/11/2009

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: **Footings / Stumps**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Base Batten  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Formwork to retain soil / pavement away from the pier and beam footing system. Not visible 2016 inspection

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Ceiling linings to balcony walkways (level 2) and main stairway

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: **Eaves / External Ceilings**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Not Identified

FINISH TYPE: Un-painted

FRIABILITY: Non Friable

CONDITION: Is In Medium Condition

ACCESSIBILITY: Is Accessible

infill panels to window recesses

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: **External Walls**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Not Identified

FINISH TYPE: Un-painted

FRIABILITY: Non Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Is Accessible

garden walls and soil retaining in planter boxes

CATEGORY: 5

RECOMMENDED ACTION:

ACTION TAKEN: Removed and replaced with non-asbestos material

DATE:

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: **Air Conditioning Duct**

MATERIAL TYPE: Asbestos Based Mastic

QUANTITY: Not Identified

USE: Air Conditioning Duct Gasket

FINISH TYPE: Natural

FRIABILITY: Non Friable

CONDITION: Is In Unknown Condition

ACCESSIBILITY: Has No Access For Observation

Mastic sealant to original aircon duct flange joints may have contained asbestos take caution if working upon

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02**

ELEMENT TYPE: External Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 7 (square metres)  
USE: Cladding Above Windows  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is on the western wall of room 25 above windows. Informed by Security asbestos removed in 2008.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 050**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 052**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 12 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 202**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: No Asbestos

Fume extractor hood above bench - Plasterboard lined.

---

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 202**

ELEMENT TYPE: **Kiln**  
MATERIAL TYPE: Asbestos Sheathed Wiring  
QUANTITY: Not Identified  
USE: Wiring Insulation  
FINISH TYPE: Natural  
FRIABILITY: Friable  
CONDITION: Is In Unknown Condition  
ACCESSIBILITY: Has Limited Access

Ward kiln Serial No:7927 likley to contain asbestos products

CATEGORY: 5  
RECOMMENDED ACTION: Use care during maintenance, replace if damaged  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 203**

ELEMENT TYPE: **Fume Cupboard**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 4 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

SAMIS Plans 2014 original fume cabinet not visible to area 203 Unit located central to area 202

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 203**

ELEMENT TYPE: **Loose Equipment**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 5 (<0.5 square metres)  
USE: Thermal Insulation  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Base to gas hot plate not located 2005 inspection

CATEGORY: 5

RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 203**

ELEMENT TYPE: Furniture  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 2 (square metres)  
USE: Bench Tops  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE: 01/02/2006

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 206**

ELEMENT TYPE: Furniture  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified (<0.5 square metres)  
USE: Refer To Memo  
FINISH TYPE: Unknown  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is on the dentistry display

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 212**

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: 21 (square metres)  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

SAMIS Plans 2014 room 212 vinyl floor tiles not visible carpet tiles on concrete

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 216**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

SAMIS Plans 2014 No visible Fume Hood to this area

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 217**

ELEMENT TYPE: **Warm Air Furnace**  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

This is on the 'howmedia' conveyor

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 217**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

This is in a disused piece of dental equipment

CATEGORY: 5  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 223**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 2 > Room 224**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 12 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Female toilet - partitions.

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 02 > Level 3 > Room 301**

ELEMENT TYPE: **Hot Water Service**  
MATERIAL TYPE: Asbestos Cement Pipe  
QUANTITY: 6 (metres)  
USE: Flue  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Hot water units--2 off Noted removed 2016 inspection

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03**

ELEMENT TYPE: **Building Exterior**  
MATERIAL TYPE: No Asbestos

Non asbestos black caulking to base of building and pavement as tested 2014 by AEC No:78989

---

**ASSET: Gilles Plains Campus > Building 03**

ELEMENT TYPE: **Air Conditioning Duct**  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Air Conditioning Duct Gasket  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Generally Inaccessible

Asbestos containing mastic sealant as tested AEC 2015- No:78989 Plant room 218 to original airconditioning duct flange joints

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 1**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

infill panels to window recesses

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 1**

ELEMENT TYPE: **External Walls**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Not Identified  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Planter boxes - retaining walls to underside of building.

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Removed By Licensed Contractor  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 1**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Ceiling linings to balcony walkways and main stairway

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 1 > Room 015**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 1 > Room 016**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 204**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning

FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 205**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 210**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 2 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 212**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Toilet partition.

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 215**

ELEMENT TYPE: **Air Conditioning Duct**  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Air Conditioning Duct Gasket  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has No Access For Observation

Asbestos containing mastic sealant to aircon flange joints as tested 2014 by AEC south of entry 215 to auditorium area 217 Report No:78989

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 218**

ELEMENT TYPE: **Hot Water Service**  
MATERIAL TYPE: Asbestos Cement Pipe  
QUANTITY: 9 (metres)  
USE: Flue  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

Replaced with metal pipe.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 218**

ELEMENT TYPE: **Room Interior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 2 (square metres)  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is stored in this room

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 218**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 12 (square metres)  
USE: Partitioning  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Enclosure , Hot water services on eastern wall

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 218**

ELEMENT TYPE: **Air Conditioning Duct**  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Caulking  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Black mastic sealant to duct flange joints as marked sample 2 tested non asbestos AEC 2014 No:78989 Note sample 1 asbestos containing 2014

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 218**

ELEMENT TYPE: **Air Conditioning Duct**  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Caulking  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Asbestos containing mastic sealant to duct flange joints as marked sample 1 tested 2014 AEC No: 78989

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 03 > Level 2 > Room 221**

ELEMENT TYPE: **Floors**  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: 10 (square metres)  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Brown flecked vinyl floor tiles as tested AEC 2015 No:

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04**

ELEMENT TYPE: **Air Conditioning Duct**  
MATERIAL TYPE: Asbestos Based Mastic  
QUANTITY: Not Identified  
USE: Air Conditioning Duct Gasket  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Unknown Condition  
ACCESSIBILITY: Has No Access For Observation

Mastic sealant to original aircon duct flange joints may have contained asbestos take caution if working upon

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04**

ELEMENT TYPE: **External Walls**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Not Identified  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Planter boxes - retaining walls to underside of building

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Removed By Licensed Contractor  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

infill panels to window recesses

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04**

ELEMENT TYPE: **Eaves / External Ceilings**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Ceiling linings to balcony walkways main stairway

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04**

ELEMENT TYPE: **Footings / Stumps**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Base Batten  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Formwork to retain soil / pavement away from the pier and beam footing system not generally visible. Not visible 2016 inspection

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 002**

ELEMENT TYPE: **Appliances**

MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Oven Door Seal  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

This is in the selby oven

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 002**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Oven Lining  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is in the selby oven

CATEGORY: 5  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 013**

ELEMENT TYPE: **Internal Doors**  
MATERIAL TYPE: Asbestos Plaster Board  
QUANTITY: Not Identified  
USE: Fire Door  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

Fire door - removed during building upgrade.

CATEGORY: 5  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 016**

ELEMENT TYPE: **Fume Cupboard**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Internal Wall Lining

FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Removed during building upgrade.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 016**

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: 1 (square metres)  
USE: Thermal Insulation  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Labmaster oven ---not found during survey 21-07-04-- or 2005 inspection

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 016**

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Oven Door Seal  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is in the four "Laboro" oven ---not found during survey 21-07-04---or 2005 inspection.

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 016**

ELEMENT TYPE: **Room Interior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Unknown  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition

ACCESSIBILITY: Is Accessible

This is various asbestos products stored in the racks

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 016**

ELEMENT TYPE: **Laboratory Equipment**

MATERIAL TYPE: Asbestos Textile Cloth

QUANTITY: Not Identified

USE: Heat Proof Mats

FINISH TYPE: Un-painted

FRIABILITY: Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Is Accessible

These mats are in a plastic bag on top of the bench

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 025**

ELEMENT TYPE: **Internal Walls**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Internal Wall Lining

FINISH TYPE: Painted

FRIABILITY: Non Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Is Accessible

Repair the damage as soon as practicable

CATEGORY: 5

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 027**

ELEMENT TYPE: **Appliances**

MATERIAL TYPE: Asbestos Rope

QUANTITY: Not Identified

USE: Oven Door Seal

FINISH TYPE: Not Identified

FRIABILITY: Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Has Limited Access

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 027**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Oven Lining  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 033**

ELEMENT TYPE: **Infill Panels**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 4 (square metres)  
USE: Ceiling Panels  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

8 panels in total Removed during building upgrade - 2006.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 038**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 039**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 174**

ELEMENT TYPE: **Toilet Cubicle**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

SAMIS Building plans 2014

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 176**

ELEMENT TYPE: **Toilet Cubicle**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

SAMIS Building plans 2014

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 1 > Room 181**

ELEMENT TYPE: **Verandah**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 60 (square metres)

USE: Ceiling Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Original verandah ceiling linings

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 2 > Room 221**

ELEMENT TYPE: **Toilet Cubicle**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04 > Level 2 > Room 223**

ELEMENT TYPE: **Toilet Cubicle**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **External Walls**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Not Identified  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Planter boxes retaining walls

CATEGORY: 5

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN: Removed By Licensed Contractor

DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **External Walls**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Wall Cladding

FINISH TYPE: Painted

FRIABILITY: Non Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Has Limited Access

This is above the roller doors

CATEGORY: 5

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN: Material Removed

DATE: 01/02/2006

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **Air Conditioning Duct**

MATERIAL TYPE: Asbestos Based Mastic

QUANTITY: Not Identified

USE: Air Conditioning Duct Gasket

FINISH TYPE: Natural

FRIABILITY: Non Friable

CONDITION: Is In Unknown Condition

ACCESSIBILITY: Has No Access For Observation

Mastic sealant to original aircon duct flange joints may have contained asbestos take caution if working upon

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **Footings / Stumps**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Base Batten

FINISH TYPE: Un-painted

FRIABILITY: Non Friable

CONDITION: Is In Medium Condition

ACCESSIBILITY: Is Accessible

Formwork to retain soil / pavement away from the pier and beam footing system. Removed from the external ( furthest

edge from the building ). 2016 only visible external to north elevation of room 37

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **Eaves / External Ceilings**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Ceiling Lining

FINISH TYPE: Un-painted

FRIABILITY: Non Friable

CONDITION: Is In Medium Condition

ACCESSIBILITY: Has Limited Access

Verandah ceiling linings to balcony walkways and main stairways

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **Floors**

MATERIAL TYPE: Vinyl Tile Containing Asbestos

QUANTITY: Not Identified

USE: Floor Covering

FINISH TYPE: Natural

FRIABILITY: Non Friable

CONDITION: Is In Medium Condition

ACCESSIBILITY: Is Accessible

Asbestos containing brown vinyl floor tiles through building as tested 2014 by XRD method Report No:78989. Rooms 17, 18, 19 & 20 removed by McMahoons 24/6/16

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: **Eaves / External Ceilings**

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Ceiling Lining

FINISH TYPE: Un-painted

FRIABILITY: Non Friable

CONDITION: Is In Medium Condition

ACCESSIBILITY: Has Limited Access

infill panels to window recesses

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A**

ELEMENT TYPE: External Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Wall Cladding  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Located outside room 25.

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 011**

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 011**

ELEMENT TYPE: Internal Doors  
MATERIAL TYPE: Asbestos Plaster Board  
QUANTITY: 2 (each)  
USE: Fire Door  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Fire doors west elevation of room to area 7. Replaced with non asbestos doors.

CATEGORY: 5  
RECOMMENDED ACTION: Use care during maintenance, replace if disturbed  
ACTION TAKEN: Removed By Licensed Contractor  
DATE: 24/06/2016

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 011**

ELEMENT TYPE: **Verandah**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 40 (square metres)  
USE: Ceiling Panels  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 011**

ELEMENT TYPE: **Building Exterior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 3 (square metres)  
USE: Infill panel above door  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

Infill panel above external roller door south elevation

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 012**

ELEMENT TYPE: **Floors**  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 013**

ELEMENT TYPE: **Floors**  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified

USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 016

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

---

ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 025

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Wall Cladding  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Located to South wall

CATEGORY: 5

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN: Material Removed

DATE:

---

ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 036

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 037**

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 038**

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 039**

ELEMENT TYPE: Floors  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 040**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 044**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 045**

ELEMENT TYPE: **Floors**  
MATERIAL TYPE: Vinyl Tile Containing Asbestos  
QUANTITY: Not Identified  
USE: Floor Covering  
FINISH TYPE: Natural  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 052**

ELEMENT TYPE: **Building Exterior**  
MATERIAL TYPE: No Asbestos

Non asbestos infill panels above roller door west elevation as tested TEMS 2016 003/56004

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 052**

ELEMENT TYPE: **Furniture**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Bench Tops  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 052**

ELEMENT TYPE: **Building Interior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Infill panel above door  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

500mm wide infill panel top of wall to roof above roller door west elevation of room 52 no confirmation of removal treat as asbestos unless tested otherwise

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 053**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Oven Door Seal  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 054**

ELEMENT TYPE: **Appliances**  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Oven Door Seal  
FINISH TYPE: Not Identified

FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Building 07 > Level 1**

ELEMENT TYPE: External Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 2 (square metres)  
USE: Not Identified  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

vermin board /soil retaining board. Vermin boards to west side (remaining 2mtr) loose. Recommend: remove & dispose of remaining boards. HSE 25/11/2009.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Shed 09**

ELEMENT TYPE: Conversion  
MATERIAL TYPE: Not Identified  
QUANTITY: Not Identified  
USE: Not Identified  
FINISH TYPE: Not Identified  
FRIABILITY: Not Identified  
CONDITION: Not Identified  
ACCESSIBILITY: Not Identified

Shed has been removed from site

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

---

**ASSET: Gilles Plains Campus > Shed 10**

ELEMENT TYPE: Conversion  
MATERIAL TYPE: Not Identified  
QUANTITY: Not Identified  
USE: Not Identified  
FINISH TYPE: Not Identified  
FRIABILITY: Not Identified  
CONDITION: Not Identified  
ACCESSIBILITY: Not Identified

Shed has been removed from site

CATEGORY: 5

RECOMMENDED ACTION:

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Shed 12**

ELEMENT TYPE: Room Interior

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified

USE: Refer To Memo

FINISH TYPE: Unknown

FRIABILITY: Non Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Is Accessible

This is loose sheets stored in this room

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable

ACTION TAKEN: Material Removed

DATE:

---

**ASSET: Gilles Plains Campus > Building 10**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Building 11**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Building 12**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 01**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 02**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 03**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 04**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 05**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 06**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 07**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 08**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 16**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 19**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 20**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 21**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 22**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

**ASSET: Gilles Plains Campus > Shed 23**

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Building 02 > Level 1 > Room 016**

ELEMENT TYPE: **Furniture**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 2 (square metres)  
USE: Bench Tops  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: **Gilles Plains Campus > Building 02 > Level 1 > Room 016**

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: 1 (square metres)  
USE: Oven Lining  
FINISH TYPE: Painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Oven with glass sliding doors --serial number S008145 ( GPBS G2027 ) Not found 2007 possibly in storage

**CATEGORY: 2**  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: **Gilles Plains Campus > Building 02 > Level 1 > Room 017**

ELEMENT TYPE: **Fume Cupboard**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 4 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 017

ELEMENT TYPE: Laboratory Equipment  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: 3 (metres)  
USE: Oven Door Seal  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Labmaster incubator - removed from the site.

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 017

ELEMENT TYPE: Laboratory Equipment  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: 3 (metres)  
USE: Oven Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Selbys Incubator (Laboro) not located during the 2006 + 2007 inspection.

**CATEGORY: 2**  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 018

ELEMENT TYPE: Laboratory Equipment

MATERIAL TYPE: Asbestos Textile Cloth  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is mats stored in the cupboards

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 029

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 6 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is the shower alcove

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 037

ELEMENT TYPE: Laboratory Equipment  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: Not Identified  
USE: Oven Door Seal  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable

DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

**DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 037**

ELEMENT TYPE: **Fume Cupboard**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Wall Cladding  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Cladding to fume cupboard.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

**DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 038**

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Textile Cloth  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Not Identified  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is the wire mats stored in the cupboards

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

**DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 038**

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: Not Identified  
USE: Thermal Insulation  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is on the "analitie" hot plate heater

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 038

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Millboard  
QUANTITY: Not Identified  
USE: Thermal Insulation  
FINISH TYPE: Natural  
FRIABILITY: Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

SEM hotplate serial no 537 millboard disc 150 x 10mm

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 048

ELEMENT TYPE: **Ceiling**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 30 (square metres)  
USE: Ceiling Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 048

ELEMENT TYPE: **Internal Walls**

MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 6 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

High level walling

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 050

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 12 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Female toilet - partitions.

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 052

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 9 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

Male toilet - partitions.

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 061

ELEMENT TYPE: Ceiling  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 2 (square metres)  
USE: Ceiling Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

Canite tiles over

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 062

ELEMENT TYPE: Ceiling  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 20 (square metres)  
USE: Ceiling Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

Canite tiles over

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

DISPOSED ASSET: Gilles Plains Campus > Building 02 > Level 1 > Room 062

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 20 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable

CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

High level walls.

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unsuitable  
DISPOSAL ACTION: Renumbered  
DISPOSAL DATE: 07/11/2008

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04 > Level 3 > Room 312**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 10 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Replaced  
DISPOSAL DATE: 19/07/2007

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04 > Level 3 > Room 313**

ELEMENT TYPE: **Internal Walls**  
MATERIAL TYPE: Compressed Asbestos Cement Sheet  
QUANTITY: 10 (square metres)  
USE: Partitioning  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unserviceable  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 19/07/2007

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04 > Level 4 > Room 401**

ELEMENT TYPE: **Hot Water Service**

MATERIAL TYPE: Asbestos Cement Pipe  
QUANTITY: 6 (metres)  
USE: Flue  
FINISH TYPE: Not Identified  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Has Limited Access

1 off.

CATEGORY: 5  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 23/07/2007

---

DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 001

ELEMENT TYPE: Fume Cupboard  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 28/09/2006

---

DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 024

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Wall Cladding  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

High level infill above roller door and windows rooms 64+24

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Not Required

DISPOSAL ACTION: Removed  
DISPOSAL DATE: 24/06/2016

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 028**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 20 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Wall linings to spray booth

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Not Required  
DISPOSAL ACTION: Removed  
DISPOSAL DATE: 24/06/2016

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 029**

ELEMENT TYPE: Internal Walls  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 20 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Un-painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Is Accessible

Internal wall linings to spray booths

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Not Required  
DISPOSAL ACTION: Removed  
DISPOSAL DATE: 24/06/2016

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 030**

ELEMENT TYPE: Fume Cupboard  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 5 (square metres)  
USE: Internal Wall Lining  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN: Material Removed

DATE:

DISPOSAL REASON: Not Required

DISPOSAL ACTION: Removed

DISPOSAL DATE: 24/06/2016

---

DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 032

ELEMENT TYPE: Internal Walls

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: 20 (square metres)

USE: Internal Wall Lining

FINISH TYPE: Painted

FRIABILITY: Non Friable

CONDITION: Is In Medium Condition

ACCESSIBILITY: Is Accessible

CATEGORY: 4

RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade

ACTION TAKEN:

DATE:

DISPOSAL REASON: Not Required

DISPOSAL ACTION: Removed

DISPOSAL DATE: 24/06/2016

---

DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 034

ELEMENT TYPE: Laboratory Equipment

MATERIAL TYPE: Asbestos Rope

QUANTITY: 3 (metres)

USE: Oven Door Seal

FINISH TYPE: Un-painted

FRIABILITY: Friable

CONDITION: Is In Good Condition

ACCESSIBILITY: Is Accessible

Laboro oven----gone to salvage

CATEGORY: 5

RECOMMENDED ACTION: Remove as soon as practicable

ACTION TAKEN: Material Removed

DATE:

DISPOSAL REASON: Surplus to Requirements

DISPOSAL ACTION: Demolished

DISPOSAL DATE: 04/12/2007

---

DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 034

ELEMENT TYPE: Furniture

MATERIAL TYPE: Asbestos Cement Sheet

QUANTITY: Not Identified  
USE: Bench Tops  
FINISH TYPE: Unknown  
FRIABILITY: Non Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 04/12/2007

---

**DISPOSED ASSET: Gilles Plains Campus > Building 04A > Level 1 > Room 049**

ELEMENT TYPE: **Laboratory Equipment**  
MATERIAL TYPE: Asbestos Rope  
QUANTITY: 3 (metres)  
USE: Oven Door Seal  
FINISH TYPE: Un-painted  
FRIABILITY: Friable  
CONDITION: Is In Good Condition  
ACCESSIBILITY: Is Accessible

This is in the Laboro oven--stored in room 34 ---gone to salvage 21-07-04

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 28/09/2006

---

**DISPOSED ASSET: Gilles Plains Campus > Building 06**

This building was not included in the survey/inspection.

ELEMENT TYPE: **Roof**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: 15 (square metres)  
USE: Fascia  
FINISH TYPE: Painted  
FRIABILITY: Non Friable  
CONDITION: Is In Medium Condition  
ACCESSIBILITY: Has Limited Access

CATEGORY: 4  
RECOMMENDED ACTION: Monitor, remove if damaged or during upgrade  
ACTION TAKEN:  
DATE:

DISPOSAL REASON: Unserviceable  
DISPOSAL ACTION: Demolished

DISPOSAL DATE: 14/01/2006

---

**DISPOSED ASSET: Gilles Plains Campus > Shed 11**

This building was not included in the survey/inspection.

ELEMENT TYPE: **Conversion**  
MATERIAL TYPE: Not Identified  
QUANTITY: Not Identified  
USE: Not Identified  
FINISH TYPE: Not Identified  
FRIABILITY: Not Identified  
CONDITION: Not Identified  
ACCESSIBILITY: Not Identified

Shed has been removed from site

CATEGORY: 5  
RECOMMENDED ACTION:  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 21/09/2006

---

**DISPOSED ASSET: Gilles Plains Campus > Shed 13**

This building was not included in the survey/inspection.

ELEMENT TYPE: **Room Interior**  
MATERIAL TYPE: Asbestos Cement Sheet  
QUANTITY: Not Identified  
USE: Refer To Memo  
FINISH TYPE: Unknown  
FRIABILITY: Non Friable  
CONDITION: Is In Poor Condition  
ACCESSIBILITY: Is Accessible

The asbestos cement sheet is adjacent to this shed

CATEGORY: 5  
RECOMMENDED ACTION: Remove as soon as practicable  
ACTION TAKEN: Material Removed  
DATE:

DISPOSAL REASON: Surplus to Requirements  
DISPOSAL ACTION: Demolished  
DISPOSAL DATE: 21/09/2006

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Building 6**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Building 6**

This building was not included in the survey/inspection.

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Shed 01**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Shed 01**

This building was not included in the survey/inspection.

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Shed 02**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Shed 02**

This building was not included in the survey/inspection.

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Shed 15**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Shed 15**

This building was not included in the survey/inspection.

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Shed 16**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Shed 16**

This building was not included in the survey/inspection.

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Shed 17**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Shed 17**

This building was not included in the survey/inspection.

ELEMENT TYPE:

No containing products were identified for this Building and child assets of this Building.

---

CATEGORY: **DISPOSED ASSETS**

LOCATION: **Gilles Plains Campus > Shed 18**  
**LT 51 Blacks Road , GILLES PLAINS, SA, 5086**

---

DISPOSED ASSET: **Gilles Plains Campus > Shed 18**

This building was not included in the survey/inspection.

ELEMENT TYPE:



No containing products were identified for this Building and child assets of this Building.

---

# Appendix E


## Site Topography

# Regional Topography
























Compiled: 18-Apr-2019  
 Generated at: [www.naturemaps.sa.gov.au](http://www.naturemaps.sa.gov.au)  
 Datum: Geocentric Datum of Australia, 1994  
 Projection: Web Mercator (Auxiliary Sphere)


Copyright © Department for Environment and Water 2019. All Rights Reserved. All works and information displayed are subject to Copyright. For the reproduction or publication beyond that permitted by the Copyright Act 1968 (Cwth) written permission must be sought from the Department. Although every effort has been made to ensure the accuracy of the information displayed, the Department, its agents, officers and employees make no representations, either express or implied, that the information displayed is accurate or fit for any purpose and expressly disclaims all liability for loss or damage arising from reliance upon the information displayed.

[illegible]


## Adelaide Soil Metropolitan Region Map Legend:

	AL: Layered stream alluvium-silts, sands and gravels.
	BE: Black to dark grey clay soils with coarse blocky structure over brown or mottled clay, variable lime. Cracking soil.
	BS: Brown sandy to clayey soils with abundant earthy lime and calcrete in subsoil.
	DS1: Layered old dune sands, generally compact and normally brown colours.
	DS2: Recent coastal dune sands, unconsolidated grey to white and yellow colours.
	EMS: Layered sediments of mixed marine and river origin-sands, silts, clays and organic deposits.
	P1: Grey sand topsoils over mottled sandy clays with blocky structure on sandstone.
	P2: Grey sandy surface over yellow and mottled clay with blocky structure on slates, shales and quartzites.
	P4: Grey sandy surface with much ironstone gravel over yellow and mottled clay with granular structure.
	Poorly drained grey soils with AL: Layered stream alluvium-silts, sands and gravels.
	RB1: Shallow stony red-brown clay soils overlying bedrock.
	RB2: Red-brown sandy clay soils with granular structure.
	RB3: Heavy red-brown clay soils with prismatic or blocky structure over clay with variable lime.
	RB4: Shallow red-brown clay soils with thin lime or calcrete layer on calcareous bedrock.
	RB5: Red-brown clay soils with granular structure over clay with variable lime.
	RB6: Red-brown clay or sandy clay soils with blocky structure with low lime sand increasing with depth.
	RB9: Mottled silty clay over brown silty clay with granular structure, slight lime, becoming sandy with depth.
	RZ: Intergrades of uniform dark brown to black soils with granular structure on highly calcareous parent material.
	RZ: Uniform dark brown to black soils with granular structure on highly calcareous parent material.
	SK: Very thin soils on bedrock. Rock outcrops general.
	water

# 1:100,000 Geological Map




April 18, 2019




Published by, and with the authority of, the Government of South Australia. Base map Attribution: Local SA Government of South Australia and ESR

Disclaimer: Although every effort has been made to ensure the accuracy of the information displayed, the Department, its agents, officers and employees make no representations, either express or implied, that the information displayed is accurate or fit for any purpose and expressly disavows all liability for loss or damage arising from reliance upon the information displayed. <http://www.energymining.sa.gov.au/bottomlinks/disclaimer>

# Shallow Groundwater Depth Map



April 18, 2019





Published by, and with the authority of, the Government of South Australia. Base map Attribution: Local SA Government of South Australia and ESR

Disclaimer: Although every effort has been made to ensure the accuracy of the information displayed, the Department, its agents, officers and employees make no representations, either express or implied, that the information displayed is accurate or fit for any purpose and expressly disclaims all liability for loss or damage arising from reliance upon the information displayed. <http://www.energy.mining.sa.gov.au/bottomlinks/disclaimer>

# Shallow Groundwater Salinity Map



April 18, 2019




Published by, and with the authority of, the Government of South Australia. Base map Attribution: Local SA Government of South Australia and ESR

Disclaimer: Although every effort has been made to ensure the accuracy of the information displayed, the Department, its agents, officers and employees make no representations, either express or implied, that the information displayed is accurate or fit for any purpose and expressly disclaims all liability for loss or damage arising from reliance upon the information displayed. <http://www.energymining.sa.gov.au/bottomlinks/disclaimer>

# Surface Water Features Map



- Water Courses
- Water Bodies
  - Dam
  - Lake - Intermittent
  - Lake - Mainly Dry
  - Lake - Perennial
- Land Subject to Flooding (STF)
- Land Subject to Inundation (STI)
- Reservoir



Compiled: 18-Apr-2019  
Generated at: [www.naturemaps.sa.gov.au](http://www.naturemaps.sa.gov.au)  
Datum: Geocentric Datum of Australia, 1994  
Projection: Web Mercator (Auxiliary Sphere)

Copyright © Department for Environment and Water 2019. All Rights Reserved. All works and information displayed are subject to Copyright. For the reproduction or publication beyond that permitted by the Copyright Act 1968 (Cwth) written permission must be sought from the Department. Although every effort has been made to ensure the accuracy of the information displayed, the Department, its agents, officers and employees make no representations, either express or implied, that the information displayed is accurate or fit for any purpose and expressly disclaims all liability for loss or damage arising from reliance upon the information displayed

# Appendix F

## Groundwater Data

**Appendix F**  
**Registered Groundwater Bore Search Results Summary**  
TAFE Gilles Plains  
17 April 2019

Approximate Distance from site (m)	Approximate Direction from site	ID	Obs Well No.	Class	Aquifer	Max drill depth (m)	Max drill date	Purpose	Latest status	Latest Status Date	SWL (m)	RSWL (m)	Water level date	TDS (mg/L)	pH	Yield (L/s)	Decimal longitude	Decimal latitude (negative)	Original Plan	Original Parcel	Original Title
350	NNE	6628-14561	-	ENG	-	9.75	18/03/1983	INV	ABD	30393	-	-	-	-	-	-	138.65344	-34.8491131	-	-	-
410	WNW	6628-9620	-	ENG	-	16.92	9/06/1967	-	UKN	24632	-	-	-	-	-	-	138.64796	-34.8502601	D51099	A3001	CR 6118 89
480	WSW	6628-16186	-	WW	Qpah	35	10/12/1992	OBSREC	OPQ	11/08/2016	0	79.33	-	3586	7.7	15	138.64731	-34.8540455	D39600	A2035	CT 5188 829
510	NE	6628-20701	-	WW	N	108	20/07/2001	-	-	-	24	67.05	20/07/2001	-	-	0.05	138.65542	-34.848406	F127388	A54	CT 6075 584
530	SE	6628-9638	-	WW	-	60.96	11/12/1951	-	BKF	18973	-	-	-	-	-	-	138.65544	-34.8557691	C40270	-	-
550	SW	6628-16185	-	WW	NE	80.5	5/12/1992	MAR	OPQ	42593	14	64.36	33943	1737	7.3	3	138.64856	-34.8560801	D39600	A2035	CT 5188 829
570	NW	6628-6902	-	ENG	-	15.24	16/06/1967	-	UKN	24639	-	-	-	-	-	-	138.64757	-34.8483331	D51099	A3001	CR 6118 89
650	NE	6628-20679	-	WW	-	196	20/07/2001	IRR	BKF	20/07/2001	24	69.95	37092	4537	-	0.25	138.65627	-34.847277	F127388	A54	CT 6075 584
660	NNE	6628-20700	-	WW	Nb	100	13/10/2001	IRR	-	-	-	-	-	3909	8.1	3.75	138.65528	-34.846699	F127388	A54	CT 6075 584
670	SW	6628-9621	-	ENG	-	-	-	-	-	-	-	-	-	-	-	-	138.64738	-34.8566862	-	-	-
690	WSW	6628-14564	-	ENG	-	9	23/03/1983	INV	ABD	30398	-	-	-	-	-	-	138.64531	-34.8549152	-	-	-
700	WSW	6628-16486	-	WW	NE	80	14/10/1993	MAROBS	OPQ	42593	-	-	-	1446	7.7	3.13	138.64505	-34.8547212	D49858	A1378	CT 5576 170
750	SSE	6628-12247	YAT091	WW, ENG	Qpah(Q1)	10.5	24/03/1983	INV	ABD	30399	-	-	36968	-	-	-	138.65526	-34.8581811	D44150	A200	CT 5548 650
770	NNE	6628-23564	-	WW	-	7	27/04/2007	INV	BKF	39394	-	-	-	-	-	-	138.65531	-34.8455893	C28370	-	-
780	NNE	6628-22796	-	WW	-	36	2/02/2006	MON	-	-	31.4	63.14	2/02/2006	-	-	-	138.65558	-34.845594	C28370	-	-
780	NNE	6628-23563	-	WW	-	6	27/04/2007	INV	BKF	39394	-	-	-	-	-	-	138.65529	-34.845501	C28370	-	-
780	NNE	6628-23565	-	WW	-	5	27/04/2007	INV	BKF	8/11/2007	-	-	-	-	-	-	138.65542	-34.8455877	C28370	-	-
790	E	6628-12851	-	WW	-	24.5	2/04/1984	-	ABD	-	-	-	-	-	-	-	138.66065	-34.85266	D3319	A113	CT 5638 750
790	NNE	6628-23562	-	WW	-	6	27/04/2007	INV	BKF	39394	-	-	-	-	-	-	138.65527	-34.8453828	C28370	-	-
830	SSW	6628-14562	-	ENG	-	10.5	21/03/1983	INV	ABD	30396	-	-	-	-	-	-	138.64842	-34.8588432	F127351	A17	CT 5853 521
830	W	6628-18900	-	WW	-	91	11/03/1998	ENVRCL	ABD	35865	-	-	-	2944	-	1.88	138.64291	-34.8512082	D48652	A360	CR 6118 88
870	SE	6628-9639	-	ENG	-	-	-	-	-	-	-	-	-	-	-	-	138.65862	-34.8575521	D26590	A103	CT 5394 850
890	NNW	6628-6961	-	WW	-	37.19	3/07/1957	-	-	-	-	-	-	4090	-	-	138.64825	-34.8445321	-	-	-
960	NE	6628-26515	-	WW	-	20	7/12/2012	INV	-	-	17	-	7/12/2012	-	-	0	138.65993	-34.8462506	D7660	A294	CT 5343 82
960	NE	6628-26710	-	WW	-	16	10/08/2012	INV	-	-	9.5	-	41131	-	-	-	138.65972	-34.8461111	-	-	-
970	NE	6628-26512	-	WW	-	18	5/12/2012	INV	-	-	16.5	-	41248	-	-	0	138.65956	-34.8457957	F127399	A65	CT 5800 591
980	SW	6628-9619	-	MW	-	14.63	13/06/1950	-	-	-	-	-	-	-	-	-	138.64519	-34.8588252	D40993	A4	CT 5235 274
980	NE	6628-26712	-	WW	-	19	9/08/2012	INV	-	-	16.5	-	9/08/2012	-	-	-	138.66	-34.8461111	D7660	A295	CT 5441 118
1000	W	6628-18899	-	WW	NE	84	11/03/1998	ENVRCL	-	-	31	54.83	35865	2909	-	10	138.64095	-34.851887	D48652	A353	CT 5906 443
1000	NE	6628-26709	-	WW	-	16.5	3/08/2012	INV	-	-	11.5	-	41124	-	-	-	138.66	-34.8458333	D7660	A296	CT 5614 463
1020	NE	6628-26514	-	WW	-	18	5/12/2012	INV	-	-	15	-	41248	-	-	0	138.6605	-34.84608	D7660	A298	CT 5931 223
1030	W	6628-11715	-	ENG	-	3.75	5/03/1981	-	ABD	-	-	-	-	-	-	-	138.64066	-34.8527152	D48652	A353	CT 5906 443
1030	NE	6628-26513	-	WW	-	16	6/12/2012	-	-	-	-	-	-	-	-	-	138.65997	-34.8453785	D9036	A6	CT 5568 63
1040	E	6628-20816	-	WW	-	26	2/07/2001	INV	-	-	18.5	80.73	37074	-	-	-	138.66331	-34.853002	-	-	-
1050	E	6628-20817	-	WW	-	26	5/07/2001	INV	-	-	18.1	80.19	37077	-	-	-	138.66333	-34.8534261	D7318	A95	CT 5735 904
1050	NE	6628-26516	-	WW	-	15	5/12/2012	INV	-	-	12	-	5/12/2012	-	-	0.01	138.66056	-34.8457372	D7660	A297	CT 5647 414
1060	W	6628-11717	-	ENG	-	4.9	5/03/1981	-	ABD	-	-	-	-	-	-	-	138.6404	-34.8525572	D48652	A353	CT 5906 443
1070	W	6628-11713	-	ENG	-	4.3	5/03/1981	-	ABD	-	-	-	-	-	-	-	138.64033	-34.8531502	D48652	A353	CT 5906 443
1070	W	6628-11714	-	ENG	-	4.5	5/03/1981	-	ABD	-	-	-	-	-	-	-	138.64028	-34.8527622	D48652	A353	CT 5906 443
1070	W	6628-11718	-	ENG	-	4.9	5/03/1981	-	ABD	-	-	-	-	-	-	-	138.64022	-34.8526162	D48652	A353	CT 5906 443
1070	E	6628-20811	-	WW	-	24	5/07/2001	INV	-	-	18.2	81.26	5/07/2001	-	-	-	138.66357	-34.8532684	D7318	A94	CT 5307 99
1070	E	6628-20812	-	WW	-	24	37078	INV	-	-	18.9	80.58	37078	-	-	-	138.66359	-34.8532958	D7318	A94	CT 5307 99
1070	E	6628-20813	-	WW	-	27	29/06/2001	INV	-	-	20.4	79.93	29/06/2001	-	-	-	138.66369	-34.8527659	D14820	A21	CT 5699 292
1080	E	6628-20814	-	WW	-	24	6/07/2001	INV	-	-	19.7	80.59	37078	-	-	-	138.66379	-34.8529029	D14820	A21	CT 5699 292
1080	NE	6628-26520	-	WW	-	12	7/12/2012	INV	-	-	8	-	41250	-	-	0	138.6599	-34.8447119	D9036	A3	CT 5555 725
1080	NE	6628-26711	-	WW	-	16.5	8/08/2012	INV	-	-	15.5	-	41129	-	-	-	138.66056	-34.8452778	D87796	A112	CT 6106 48
1090	E	6628-20804	-	WW	-	24	4/07/2001	INV	-	-	17.6	81.26	37076	-	-	-	138.66371	-34.8537668	D8293	A55	CT 5494 966
1090	E	6628-20810	-	WW	-	27	29/06/2001	INV	-	-	17.6	82.47	29/06/2001	-	-	-	138.66389	-34.8531933	D7318	A94	CT 5307 99
1090	E	6628-20815	-	WW	-	24	4/07/2001	INV	-	-	18.5	81.75	4/07/2001	-	-	-	138.66389	-34.8530582	D14820	A21	CT 5699 292
1100	NNW	6628-6962	-	WW	-	12.19	13/03/1958	-	ABD	-	-	-	-	-	-	-	138.64812	-34.8425921	S12397	-	-
1100	W	6628-11716	-	ENG	-	3.5	5/03/1981	-	ABD	-	-	-	-	-	-	-	138.63986	-34.8525552	D55895	A110	CT 5834 819
1100	E	6628-20532	-	WW	-	20.5	25/07/2000	MON	-	-	18	82.34	25/07/2000	-	-	-	138.664	-34.853105	D14820	A21	CT 5699 292
1100	E	6628-20809	-	WW	-	24	2/07/2001	INV	-	-	19.3	81.23	2/07/2001	-	-	-	138.66395	-34.852906	D14820	A21	CT 5699 292
1110	E	6628-20531	-	WW	-	20	24/07/2000	INV	-	-	18.1	82.42	36731	-	-	-	138.66412	-34.853117	D14820	A21	CT 5699 292
1120	E	6628-20530	-	WW	-	20	24/07/2000	INV	-	-	18.4	82.35	24/07/2000	-	-	-	138.66417	-34.852991	D14820	A21	CT 5699 292
1120	E	6628-20606	-	WW	-	20	2/02/2001	MON	-	-	-	-	-	-	-	-	138.66415	-34.853532	D6986	A95	CT 5539 699


Approximate Distance from site (m)	Approximate Direction from site	ID	Obs Well No.	Class	Aquifer	Max drill depth (m)	Max drill date	Purpose	Latest status	Latest Status Date	SWL (m)	RSWL (m)	Water level date	TDS (mg/L)	pH	Yield (L/s)	Decimal longitude	Decimal latitude (negative)	Original Plan	Original Parcel	Original Title
1130	E	6628-20808	-	WW	-	24	3/07/2001	INV	-	-	17.9	82.46	3/07/2001	-	-	-	138.6642	-34.8535057	D6986	A95	CT 5539 699
1130	NE	6628-26542	-	WW	-	10.4	6/12/2012	INV	-	-	7.4	-	41249	-	-	0.1	138.66134	-34.8452815	-	-	-
1160	NE	6628-6964	-	WP	-	-	-	-	-	-	-	-	-	4090	-	3.79	138.66059	-34.844302	D7614	A148	CT 6160 126
1190	WSW	6628-14563	-	ENG	-	5.25	21/03/1983	INV	ABD	30396	-	-	-	-	-	-	138.63955	-34.8553623	D70794	A22	CT 5962 289
1230	NE	6628-6965	-	WW	-	9.14	29/01/1958	-	-	-	4.57	73.43	21214	3474	-	2.53	138.66211	-34.844683	D87796	A113	CT 6160 220
1290	NNW	6628-6963	-	WP	-	-	-	-	-	-	-	-	-	3875	-	-	138.64683	-34.8411151	D6741	A41	CT 4267 574
1310	W	6628-11710	-	ENG	-	4.55	-	-	ABD	-	-	-	-	-	-	-	138.63781	-34.8540213	D45084	A300	CR 5547 146
1310	SSW	6628-27955	-	WW	-	-	8/09/2015	-	BKF	8/09/2015	-	-	-	-	-	-	138.64789	-34.86326	D115734	A2004	CT 6191 189
1350	WSW	6628-11711	-	ENG	-	5.7	-	-	ABD	-	-	-	-	-	-	-	138.63749	-34.8544113	D45084	A300	CR 5547 146
1370	W	6628-11712	-	ENG	-	6.3	-	-	ABD	-	-	-	-	-	-	-	138.6372	-34.8540723	D45084	A300	CR 5547 146
1380	WSW	6628-9605	-	WW	-	33.53	24/09/1964	-	ABD	-	-	-	-	-	-	-	138.63792	-34.8565923	D41553	A702	CT 5238 416
1380	W	6628-11709	-	ENG	-	5.75	-	-	ABD	-	-	-	-	-	-	-	138.63697	-34.8537343	D45084	A300	CR 5547 146
1400	N	6628-7157	-	ENG	-	30.56	20/04/1956	INV	UKN	20565	-	-	-	-	-	-	138.65132	-34.83939	D67138	A556	CT 5940 487
1410	NNE	6628-7006	-	WP	-	4.57	13/03/1958	-	ABD	-	-	-	-	-	-	-	138.65609	-34.839726	D6965	A48	CT 4377 565
1410	ENE	6628-13649	-	WW	Nds	252	6/05/1986	-	-	-	3.3	72.17	17/06/1986	2534	11.5	1.25	138.66497	-34.8450259	F126889	A2	CT 5294 626
1410	NNW	6628-15258	-	WW	Nds	83.8	32994	-	BKF	37400	-	-	-	1917	7.9	-	138.64825	-34.839622	D7857	A12	CT 5393 322
1410	NNW	6628-15259	-	WW	-	63	7/03/1990	-	BKF	32939	-	-	-	-	-	-	138.64829	-34.839677	D7857	A12	CT 5393 322
1450	N	6628-7159	-	ENG	-	15.39	27/04/1956	INV	UKN	20572	-	-	-	-	-	-	138.65192	-34.838915	-	-	-
1450	SSW	6628-27957	-	WW	-	-	8/09/2015	-	BKF	8/09/2015	-	-	-	-	-	-	138.64865	-34.86476	D115734	A2004	CT 6191 189
1460	N	6628-7158	-	ENG	-	30.48	13/03/1956	INV	UKN	20527	-	-	-	-	-	-	138.65105	-34.838826	D9097	A9	CT 5284 178
1480	N	6628-7005	-	WP	-	-	-	-	-	-	-	-	-	3431	-	-	138.65398	-34.838783	D6965	A48	CT 4377 565
1490	SSW	6628-9618	-	MW	-	27.28	8/06/1950	-	BKF	18422	-	-	-	-	-	-	138.64571	-34.8643612	D5518	A576	CT 5751 373
1510	N	6628-7151	-	ENG	-	21.34	16/03/1956	INV	UKN	20530	-	-	-	-	-	-	138.65143	-34.838365	D7303	A71	CT 5572 706
1510	WSW	6628-25486	-	WW	Qpah	26	6/10/2010	INV	-	-	-	-	-	-	-	-	138.6365	-34.8568043	D41554	A2101	CT 5238 445
1530	ESE	6628-9640	-	ENG	-	-	-	-	-	-	-	-	-	-	-	-	138.66848	-34.8546129	D44776	A31	CT 5323 149
1550	WNW	6628-9600	-	MW	-	39.01	16/05/1950	-	-	-	-	-	-	-	-	-	138.63537	-34.8490423	-	-	-
1550	SSW	6628-19239	-	WW	-	14.4	25/08/1998	-	BKF	36032	-	-	-	-	-	-	138.64509	-34.8647733	F127348	A14	CT 5613 639
1560	N	6628-7156	-	ENG	-	18.29	4/04/1956	INV	UKN	20549	-	-	-	-	-	-	138.65347	-34.83798	D7303	A109	CT 5376 584
1570	N	6628-7152	-	ENG	-	21.26	8/03/1956	INV	UKN	20522	-	-	-	-	-	-	138.65133	-34.837831	D7303	A84	CT 5602 8
1570	WSW	6628-9606	-	WW	NE	62.79	16/08/1944	-	ABD	-	34.14	47.71	16/08/1944	4390	-	1.26	138.63775	-34.8599253	D28260	A63	CT 5144 622
1570	SSE	6628-9637	-	WW	NE	94.49	5/06/1934	-	-	-	19.81	35.05	12575	2270	-	2.02	138.65653	-34.8656161	F11952	A23	CT 5864 791
1600	WSW	6628-9602	-	MW	-	38.1	19/04/1950	-	-	-	-	-	-	-	-	-	138.63593	-34.8577623	-	-	-
1600	SSW	6628-28070	-	WW	-	-	27/08/2014	-	BKF	41878	-	-	-	-	-	-	138.64705	-34.8658411	D22852	A2	CT 5885 188
1600	WNW	6628-28869	-	WW	-	4	10/02/2017	INV	-	-	1.5	-	42776	-	-	-	138.63517	-34.8477265	D53642	A501	CT 6136 363
1600	WNW	6628-28875	-	WW	-	3	14/02/2017	INV	-	-	1.5	-	42780	-	-	-	138.63517	-34.8477265	D53642	A501	CT 6136 363
1620	S	6628-9636	-	WW	-	50.29	3/01/1946	-	-	-	6.1	65.99	3/01/1946	1385	-	2.53	138.65391	-34.8665212	D7629	A51	CT 5590 132
1620	WNW	6628-28870	-	WW	-	4	14/02/2017	INV	-	-	1.5	-	14/02/2017	-	-	-	138.63498	-34.847624	D53642	A501	CT 6136 363
1630	W	6628-9601	-	ENG	-	18.1	9/03/1972	-	UKN	26367	-	-	-	-	-	-	138.63429	-34.8540793	D91939	A50	CT 6134 65
1630	SW	6628-9607	-	ENG	-	4.27	21/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9608	-	ENG	-	4.27	22/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9609	-	ENG	-	4.27	22/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9610	-	ENG	-	4.27	22/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9611	-	ENG	-	4.27	23/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9612	-	ENG	-	4.27	23/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9613	-	ENG	-	4.27	23/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9614	-	ENG	-	4.27	24/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	SW	6628-9615	-	ENG	-	4.27	24/10/1952	-	ABD	-	-	-	-	-	-	-	138.6406	-34.863279	D45202	A162	CT 5334 352
1630	WNW	6628-28868	-	WW	-	4	10/02/2017	INV	-	-	1.5	-	42776	-	-	-	138.63488	-34.8477502	D53642	A501	CT 6136 363
1630	WNW	6628-28871	-	WW	-	3.5	14/02/2017	INV	-	-	1.5	-	14/02/2017	-	-	-	138.63498	-34.8474103	D53642	A501	CT 6136 363
1640	N	6628-7155	-	ENG	-	21.34	28/03/1956	INV	UKN	20542	-	-	-	-	-	-	138.65303	-34.837233	D7303	A129	CT 5336 163
1640	WNW	6628-28872	-	WW	-	2.5	10/02/2017	INV	-	-	0.9	-	10/02/2017	-	-	-	138.63495	-34.8471934	D53642	A501	CT 6136 363
1640	WNW	6628-28882	-	WW	-	4	14/02/2017	INV	-	-	1	-	42780	-	-	-	138.6346	-34.8480426	D53642	A501	CT 6136 363
1650	WNW	6628-28873	-	WW	-	3	14/02/2017	INV	-	-	1	-	14/02/2017	-	-	-	138.63486	-34.8470714	D53642	A501	CT 6136 363
1660	SSE	6628-19348	-	WW	-	25	1/02/1999	DOM	ABD	36192	-	-	-	-	-	-	138.65791	-34.866148	D9434	A10	CT 5200 659
1660	SSE	6628-19349	-	WW	NE	27	2/02/1999	DOM	-	-	10	39.54	36193	1351	-	0.01	138.65791	-34.866148	D9434	A10	CT 5200 659
1660	WNW	6628-28880	-	WW	-	4	10/02/2017	INV	-	-	1.1	-	10/02/2017	-	-	-	138.63449	-34.8477631	D53642	A501	CT 6136 363
1680	N	6628-7153	-	ENG	-	21.34	20/03/1956	INV	UKN	20534	-	-	-	-	-	-	138.65197	-34.836869	D7303	A88	CT 5415 810
1680	ESE	6628-9641	-	WW	-	47	21/02/1972	-	-	-	6.5	88.56	21/02/1972	2751	-	1.14	138.66987	-34.8556589	D44776	A82	CT 5323 200
1680	WNW	6628-28874	-	WW	-	2.5	14/02/2017	INV	-	-	1.2	-	42780	-	-	-	138.63452	-34.8470863	D53642	A501	CT 6136 363
1690	S	6628-9631	-	ENG	-	3.05	24/05/1966	-	UKN	24251	-	-	-	-	-	-	138.65235	-34.867203	D7629	A41	CT 5427 170
1690	S	6628-9634	-	WW	-	60.96	17/02/1936	-	ABD	-	-	-	-	2130	-	6.32	138.65331	-34.8671322	D7629	A73	CT 5345 801
1700	SSW	6628-28067	-	WW	-	-	27/08/2014	-	BKF	41878	-	-	-	-	-	-	138.64693	-34.8666954	D22852	A2	CT 5885 188

Approximate Distance from site (m)	Approximate Direction from site	ID	Obs Well No.	Class	Aquifer	Max drill depth (m)	Max drill date	Purpose	Latest status	Latest Status Date	SWL (m)	RSWL (m)	Water level date	TDS (mg/L)	pH	Yield (L/s)	Decimal longitude	Decimal latitude (negative)	Original Plan	Original Parcel	Original Title
1700	WNW	6628-28881	-	WW	-	4	10/02/2017	INV	-	-	1.2	-	42776	-	-	-	138.634	-34.8477874	D53642	A501	CT 6136 363
1710	S	6628-9635	-	WW	-	24.38	13/11/1964	-	ABD	-	-	-	-	-	-	-	138.65368	-34.8673012	D31869	A1	CT 5418 725
1710	E	6628-12246	YAT090	WW, ENG	N	11.65	25/03/1983	INV	ABD	30400	8.47	86.53	34879	-	-	0	138.6705	-34.8546249	D44776	A11	CT 5323 129
1720	N	6628-7154	-	ENG	-	27.43	23/03/1956	INV	UKN	20537	-	-	-	-	-	-	138.65387	-34.836546	D117152	A11	CT 6200 230
1730	NNE	6628-6966	-	WW	-	7.62	3/02/1958	-	-	-	6.1	95.9	3/02/1958	4260	-	2.53	138.65768	-34.837079	D6716	A151	CT 5151 275
1730	S	6628-9633	-	WW	NE	75.29	17/02/1936	-	-	-	7.62	67.54	17/02/1936	1642	-	1.89	138.65331	-34.8674922	D31869	A1	CT 5418 725
1730	WSW	6628-19498	-	WW	Nb	81	6/03/1999	ENVREC	-	-	-	-	-	4216	-	4	138.63395	-34.8567583	-	-	-
1740	SSW	6628-21233	-	WW	T(T1)	19.5	28/03/2003	MON	-	-	16	59.92	28/03/2003	-	-	-	138.64661	-34.8670542	D22852	A2	CT 5885 188
1740	WNW	6628-28879	-	WW	-	4	9/02/2017	INV	-	-	-	-	-	-	-	-	138.63352	-34.8479387	D53642	A501	CT 6136 363
1750	S	6628-9627	-	ENG	-	3.05	26/05/1966	-	UKN	26/05/1966	-	-	-	-	-	-	138.65221	-34.8677777	D114039	A101	CT 6187 199
1750	NE	6628-13807	-	WW	Nds	121.5	2/06/1989	TWS	OPR	-	3	77.03	19/07/1989	2008	7.4	7.5	138.6675	-34.8427691	F31939	A11	CT 5294 625
1750	SW	6628-14565	-	ENG	-	9.75	28/03/1983	INV	ABD	30403	-	-	-	-	-	-	138.63857	-34.8632853	D45391	A501	CT 5374 415
1750	SSW	6628-28068	-	WW	-	-	41878	-	BKF	27/08/2014	-	-	-	-	-	-	138.64689	-34.8671632	D22852	A2	CT 5885 188
1760	W	6628-9599	-	MW	-	23.16	12/07/1950	-	-	-	-	-	-	-	-	-	138.63292	-34.8491033	-	-	-
1760	S	6628-16876	-	WW	N	103.6	9/01/1995	IND	-	-	18	57.21	34708	2570	7.3	10	138.64933	-34.8676482	D86892	A52	CT 6094 432
1760	WNW	6628-28876	-	WW	-	4	9/02/2017	INV	-	-	1.2	-	9/02/2017	-	-	-	138.63342	-34.8476712	D53642	A501	CT 6136 363
1760	WNW	6628-28878	-	WW	-	4	9/02/2017	INV	-	-	1.2	-	9/02/2017	-	-	-	138.63335	-34.8477178	D53642	A501	CT 6136 363
1760	WNW	6628-28883	-	WW	-	3.1	14/02/2017	INV	-	-	-	-	-	-	-	-	138.63356	-34.8470983	D53642	A501	CT 6136 363
1770	W	6628-11707	-	ENG	-	4.6	-	-	-	-	-	-	-	-	-	-	138.63259	-34.8515573	-	-	-
1770	WNW	6628-28877	-	WW	-	4	9/02/2017	INV	-	-	1	-	9/02/2017	-	-	-	138.63338	-34.8475074	D53642	A501	CT 6136 363
1780	WNW	6628-28884	-	WW	-	3	9/02/2017	INV	-	-	1	-	9/02/2017	-	-	-	138.63329	-34.8472041	D53642	A501	CT 6136 363
1780	ENE	6628-29319	-	WW	-	14.5	13/02/2018	MON	-	-	-	-	-	-	-	-	138.66996	-34.8456922	-	-	-
1790	SSW	6628-28069	-	WW	-	-	41880	-	BKF	29/08/2014	-	-	-	-	-	-	138.64638	-34.8673968	D22852	A2	CT 5885 188
1800	ENE	6628-27740	-	WW	-	-	-	-	-	-	-	-	-	-	-	-	138.67045	-34.8461703	-	-	-
1810	WSW	6628-9505	-	ENG	-	-	-	-	-	-	-	-	-	-	-	-	138.6334	-34.8578303	D54002	A1000	CT 5743 60
1810	SSE	6628-9680	-	WW	Qa	11.28	4/06/1935	-	ABD	-	2.9	47.12	12939	328	-	-	138.65767	-34.8676391	D6639	A61	CT 2743 48
1810	ENE	6628-27741	-	WW	-	-	-	-	-	-	-	-	-	-	-	-	138.67051	-34.8460452	-	-	-
1810	ENE	6628-29320	-	WW	-	15	13/02/2018	MON	-	-	-	-	-	-	-	-	138.67059	-34.8463623	D6065	A2	CT 5211 7
1820	W	6628-11708	-	ENG	-	4.45	-	-	-	-	-	-	-	-	-	-	138.63204	-34.8515743	D58828	A336	CT 5866 858
1820	ENE	6628-27742	-	WW	-	-	-	-	-	-	-	-	-	-	-	-	138.67058	-34.8459474	-	-	-
1820	ENE	6628-29570	-	WW	-	17	12/02/2018	MON	-	-	-	-	-	-	-	-	138.67045	-34.8457917	-	-	-
1830	SSE	6628-20251	-	WW	Qa	18	24/06/2000	DOM	-	-	6	49.49	36701	871	-	0.75	138.66126	-34.866575	D5872	A47	CT 5400 760
1840	ENE	6628-29322	-	WW	-	13	14/02/2018	MON	-	-	-	-	-	-	-	-	138.67099	-34.8462979	D6065	A1	CT 5211 6
1840	ENE	6628-29323	-	WW	-	13	14/02/2018	MON	-	-	-	-	-	-	-	-	138.67079	-34.8460778	F128629	A38	CT 5236 29
1870	ENE	6628-29321	-	WW	-	13.5	13/02/2018	MON	-	-	-	-	-	-	-	-	138.67111	-34.8458675	-	-	-
1880	S	6628-13652	-	WW	NE	154	2/05/1986	-	-	-	0	51.96	17/06/1986	2278	8.6	4	138.65538	-34.8686862	F131993	A3	CT 5870 427
1890	SW	6628-12588	YAT104	WW	NE	55.5	8/11/1983	OBS	ABD	36304	15.82	56.38	36236	523	7.6	0	138.63992	-34.8658903	D52643	A4	CT 5682 514
1910	W	6628-9506	-	MW	-	13.72	5/07/1950	CMT	-	-	-	-	-	-	-	-	138.63111	-34.8506813	D61375	A811	CT 5889 361
1910	SW	6628-12587	YAT103	WW	Qpah(Q1)	8	9/11/1983	OBS	ABD	36304	7.12	65.11	32209	-	-	-	138.64004	-34.8661443	D52643	A6	CT 5682 516
1920	ESE	6628-20778	-	WW	NE	40	1/02/2002	DOM	-	-	11	79.31	1/02/2002	2732	-	2	138.67232	-34.8566456	D70703	A61	CT 5968 528
1930	SW	6628-9617	-	ENG	-	29.87	24/03/1965	-	UKN	23825	-	-	-	-	-	-	138.6391	-34.8658383	D45881	A10	CT 5398 545
1950	ESE	6628-11705	-	ENG	-	14.95	21/02/1981	-	UKN	29638	-	-	-	-	-	-	138.67111	-34.8599379	D25194	A606	CT 5105 573
1970	SSW	6628-9622	-	WW	NE	92.96	8/07/1935	-	-	-	-	-	-	656	-	0.63	138.64598	-34.8689913	D5924	A81	CT 5521 854
1980	SW	6628-9616	-	ENG	-	15.85	29/03/1965	-	UKN	23830	-	-	-	-	-	-	138.63835	-34.8658323	D45881	A12	CT 5398 547
1980	SSE	6628-11701	-	ENG	-	10.45	12/02/1981	-	UKN	29629	-	-	-	-	-	-	138.66304	-34.8673011	-	-	-
1990	SSE	6628-9681	-	WW	NE	48.77	19/07/1943	-	-	-	39.62	15.74	15906	999	-	1.89	138.6595	-34.8687661	D6639	A18	CT 5634 626
1990	SSE	6628-11141	-	ENG	-	7.8	19/09/1979	-	UKN	29117	-	-	-	-	-	-	138.66436	-34.8667861	D28138	A43	CT 5832 277
1990	SE	6628-11703	-	ENG	-	18.8	17/02/1981	-	UKN	29634	-	-	-	-	-	-	138.665	-34.86641	D28138	A43	CT 5832 277

Key	Class Key	Aquifer Key	Count	Purpose Key	Count	Latest Status Key	Count
-	Unknown	ENG Engineering Well	2	CMT Construction Materials	1	ABD Abandoned	23
SWL	Standing Water Level	WW Water Well	3	DOM Domestic	2	BKF Backfilled	10
RSWL	Reduced Water Level	Strat Stratigraphic	12	IND Industrial	1	OPQ Operational as req	2
TDS	Total Dissolved Solids	Ne Yerelina Subgroup	2	INV Investigation	37	OPR Operational	1
m	metres	Qpah Hindmarsh Clay	2	IRR Irrigation	1	UKN Unknown	12
mg/L	milligrams per litre	Qpah(Q1) Hindmarsh Clay, Quaternary aquifer	2	MON Monitoring	6		
				OBS Observation	1		

**Data Source:**

WaterConnect (2019) Groundwater Data Online Database, Department of Environment and Water, Government of South Australia, viewed 17 April 2019, <https://www.waterconnect.sa.gov.au/GD>.



# Appendix G

## Certificates of Title

REAL PROPERTY ACT, 1886



The Registrar-General certifies that this Title Register Search displays the records maintained in the Register Book and other notations at the time of searching.



## Certificate of Title - Volume 5519 Folio 164

Parent Title(s) CT 4393/578

Creating Dealing(s) CONVERTED TITLE

Title Issued 30/03/1998 Edition 4 Edition Issued 21/03/2017

## Estate Type

FEE SIMPLE

## Registered Proprietor

URBAN RENEWAL AUTHORITY  
OF L9 RIVERSIDE CENTRE NORTH TERRACE ADELAIDE SA 5000

## Description of Land

SECTION 788  
HUNDRED OF YATALA  
IN THE AREA NAMED GILLES PLAINS

## Conditions

IN TRUST TO PERMIT SUFFER AND TO BE USED AT ALL TIMES AS A RESERVE FOR SCHOOL PURPOSES

## Easements

NIL

## Schedule of Dealings

NIL

## Notations


Dealings Affecting Title NIL

Priority Notices NIL

Notations on Plan NIL

Registrar-General's Notes NIL

Administrative Interests NIL



Orig. **T 12688838**  
  
12:30 01-Mar-2017  
1 of 2

Orig. **T 12688847**  
  
12:30 01-Mar-2017  
2 of 2

AGENT CODE

## LANDS TITLES REGISTRATION OFFICE

SOUTH AUSTRALIA

## TRANSFER

FORM APPROVED BY THE REGISTRAR-GENERAL

PRIORITY NOTICE ID

BELOW THIS LINE FOR OFFICE &  
STAMP DUTY PURPOSES ONLY

LODGED BY: CROWN SOLICITOR'S OFFICE CSOL 22

CORRECTION TO: CROWN SOLICITOR'S OFFICE CSOL 22

SUPPORTING DOCUMENTATION LODGED WITH INSTRUMENT  
(COPIES ONLY)

- 1.....
- 2.....
- 3.....
- 4.....
- 5.....

ISSUE NEW CERTIFICATE(S) OF TITLE AS FOLLOWS:

- 1.....
- 2.....
- 3.....
- 4.....
- 5.....

**CROWN INSTRUMENT**  
**NO FEES PAYABLE**

COMMISSIONER OF STATE TAXATION

S.A. STAMP DUTY PAID \$23977683.35  
ADJUDGED DUTY STAMPED  
ORIGINAL with 0 copies  
01/03/2017 12:09:53 00867065.1  
Consideration / Value (\$654049000.00)  
LAND SALE QUALIFYING

CORRECTION	PASSED 
REGISTERED 21 MAR 2017  pro REGISTRAR-GENERAL 	

# TRANSFER

**PRIVACY COLLECTION STATEMENT:** The information in this form is collected under statutory authority and is used for maintaining publicly searchable registers and indexes. It may also be used for authorised purposes in accordance with Government legislation and policy requirements.

## LAND DESCRIPTION

Refer to Attached Annexure A

## ESTATE & INTEREST

In fee simple

## TRANSFEROR (Full name and address)

**MINISTER FOR HIGHER EDUCATION AND SKILLS** as successor to the Minister for Employment, Higher Education and Skills of Adelaide SA 5000

## CONSIDERATION (Words and figures)

SIX HUNDRED AND FIFTY FOUR MILLION AND FORTY NINE THOUSAND DOLLARS (654,049,000.00) GST inclusive

## TRANSFeree (Full name, address and mode of holding)

**URBAN RENEWAL AUTHORITY** ABN 86 832 349 553 of Level 9 West Riverside Centre North Terrace  
Adelaide SA 5000

THE TRANSFEROR ACKNOWLEDGING RECEIPT OF THE CONSIDERATION, TRANSFERS TO THE TRANSFeree THE ESTATE AND INTEREST SPECIFIED IN THE LAND DESCRIBED.

DATED

28<sup>th</sup> of February 2017

## CERTIFICATION *\*delete the inapplicable*

### Transferee(s)

\*The Prescribed Person has taken reasonable steps to verify the identity of the transferee.

\*The Prescribed Person holds a properly completed Client Authorisation for the Conveyancing Transaction including this Registry Instrument or Document.

\*The Prescribed Person has retained the evidence to support this Registry Instrument or Document.

\*The Prescribed Person has taken reasonable steps to ensure that the Registry Instrument or Document is correct and compliant with relevant legislation and any Prescribed Requirement.

Signed By:



**HESTER ELIZABETH DAALDER**  
Executive Solicitor

for: Crown Solicitor's Office

on behalf of the Transferee

**Transferor(s)**

\*The Prescribed Person has taken reasonable steps to verify the identity of the transferor.

\*The Prescribed Person holds a properly completed Client Authorisation for the Conveyancing Transaction including this Registry Instrument or Document.

\*The Prescribed Person has retained the evidence to support this Registry Instrument or Document.

\*The Prescribed Person has taken reasonable steps to ensure that the Registry Instrument or Document is correct and compliant with relevant legislation and any Prescribed Requirement.

Signed By:



**HESTER ELIZABETH DAALDER**  
Executive Solicitor

**for: Crown Solicitor's Office**

**on behalf of the Transferor**

in relation to:

**LAND:** Whole of the land comprised in Certificates of Title Volume 5323 Folio 620, Volume 5352 Folio 179, Volume 5369 Folio 168, Volume 5379 Folio 38, Volume 5400, Folio 791, Volume 5441 Folio 345, Volume 5454 Folio 830, Volume 5460 Folio 129, Volume 5461 Folio 103, Volume 5474 Folio 898, Volume 5479 Folio 366, Volume 5479 Folio 367, Volume 5495 Folio 304, Volume 5485 Folio 200, Volume 5519 Folio 164, Volume 5545 Folio 164, Volume 5545 Folio 249, Volume 5554 Folio 414, Volume 5664 Folio 167, Volume 5672 Folio 808, Volume 5728 Folio 735, Volume 5750 Folio 304, Volume 5753 Folio 375, Volume 5775 Folio 333, Volume 5805 Folio 930, Volume 5810 Folio 417, Volume 5836 Folio 400, Volume 5861 Folio 937, Volume 5857 Folio 156, Volume 5883 Folio 982, Volume 5891 Folio 105, Volume 5901 Folio 746, Volume 5970 Folio 822, Volume 6007 Folio 686, Volume 6033 Folios 237 & 238, Volume 6038 Folio 684, Volume 6047 Folio 839, Volume 6078 Folio 678, Volume 6135 Folio 377, Volume 6135 Folio 382, Volume 6159 Folio 713, Volume 6170 Folio 177 and Volume 6175 Folio 379

**CONSIDERATION:** SIX HUNDRED AND FIFTY FOUR MILLION AND FORTY NINE THOUSAND DOLLARS (\$654,049,000.00)  
GST inclusive

**TRANSFEROR:** MINISTER FOR HIGHER EDUCATION AND SKILLS

**TRANSFeree:** URBAN RENEWAL AUTHORITY

838

**PRIVACY COLLECTION STATEMENT:** The information in this form is collected under statutory authority and is used for maintaining publicly searchable registers and indexes. It may also be used for authorised purposes in accordance with Government legislation and policy requirements.

To be completed by lodging party

Office Use Only

**ANNEXURE to MEM. OF TRANSFER** dated 28/2/17  
over Certificate of Title Volume:5323 Folio:620 & others

**NUMBER**

**LAND:** Whole of the land comprised in Certificates of Title Volume 5323 Folio 620, Volume 5352 Folio 179, Volume 5369 Folio 168, Volume 5379 Folio 38, Volume 5400, Folio 791, Volume 5441 Folio 345, Volume 5454 Folio 830, Volume 5460 Folio 129, Volume 5461 Folio 103, Volume 5474 Folio 898, Volume 5479 Folio 366, Volume 5479 Folio 367, Volume 5495 Folio 304, Volume 5485 Folio 200, Volume 5519 Folio 164, Volume 5545 Folio 164, Volume 5545 Folio 249, Volume 5554 Folio 414, Volume 5664 Folio 167, Volume 5672 Folio 808, Volume 5728 Folio 735, Volume 5750 Folio 304, Volume 5753 Folio 375, Volume 5775 Folio 333, Volume 5805 Folio 930, Volume 5810 Folio 417, Volume 5836 Folio 400, Volume 5861 Folio 937, Volume 5857 Folio 156, Volume 5883 Folio 982, Volume 5891 Folio 105, Volume 5901 Folio 746, Volume 5970 Folio 822, Volume 6007 Folio 686, Volume 6033 Folios 237 & 238, Volume 6038 Folio 684, Volume 6047 Folio 839, Volume 6078 Folio 678, Volume 6135 Folio 377, Volume 6135 Folio 382, Volume 6159 Folio 713, Volume 6170 Folio 177 and Volume 6175 Folio 379

**DEALING:** Estate in fee simple**TRANSFEROR:** Minister for Higher Education and Skills**TRANSFeree:** Urban Renewal Authority**LAND DESCRIPTION:**

Whole of the land comprised in Certificates of Title Volume 5323 Folio 620, Volume 5352 Folio 179, Volume 5369 Folio 168, Volume 5379 Folio 38, Volume 5400, Folio 791, Volume 5441 Folio 345, Volume 5454 Folio 830, Volume 5460 Folio 129, Volume 5461 Folio 103, Volume 5474 Folio 898, Volume 5479 Folio 366, Volume 5479 Folio 367, Volume 5495 Folio 304, Volume 5485 Folio 200, Volume 5519 Folio 164, Volume 5545 Folio 164, Volume 5545 Folio 249, Volume 5554 Folio 414, Volume 5664 Folio 167, Volume 5672 Folio 808, Volume 5728 Folio 735, Volume 5750 Folio 304, Volume 5753 Folio 375, Volume 5775 Folio 333, Volume 5805 Folio 930, Volume 5810 Folio 417, Volume 5836 Folio 400, Volume 5861 Folio 937, Volume 5857 Folio 156, Volume 5883 Folio 982, Volume 5891 Folio 105, Volume 5901 Folio 746, Volume 5970 Folio 822, Volume 6007 Folio 686, Volume 6033 Folios 237 & 238, Volume 6038 Folio 684, Volume 6047 Folio 839, Volume 6078 Folio 678, Volume 6135 Folio 377, Volume 6135 Folio 382, Volume 6159 Folio 713, Volume 6170 Folio 177 and Volume 6175 Folio 379

**ORIGINAL  
LAND GRANT**

**South Australia**

**REGISTER BOOK**

**Volume 4393 Folio 578**



*R. J. Hammon*  
**Deputy Registrar-General**

Comprising 2 Sheets

FOR SCHOOL PURPOSES

HER EXCELLENCY THE GOVERNOR doth hereby in the name and on behalf of HER MAJESTY GRANT unto MINISTER OF EMPLOYMENT AND FURTHER EDUCATION hereinafter called the Grantee ALL that Section of land containing eight point nought eight five (8.085) hectares situate in the Hundred of YATALA County of ADELAIDE and numbered 788 and delineated in L.T.R.O. Filed Plan No. 31201 filed in the Department of Lands at ADELAIDE TO HOLD unto and to the use of the Grantee his Successors and Assigns for ever in TRUST to permit and suffer the said piece of land to be used at all times as a reserve for school purposes

GIVEN under the hand of the Governor and the Public Seal of South Australia  
this      ninth      day of      December      one thousand nine hundred and ninety one

*Exd.*  
Exd.

Certified correct

D.L. 2279/37


*[Signature]*  
Chief Documentary Officer

BY COMMAND,


*[Signature]*  
The Minister of Lands

**CANCELLED**  
CONVERTED TO A COMPUTERISED TITLE





Sheet 2




0 25 50 75 100 Metres

VOL 4393 FOL 578

# Appendix H

## Historical Aerial Photographs



\\auad11fp001\AECOM\_Projects\606X\60603737\900\_CAD\_GIS\920\_GIS\FIGURES\MXD\60603737-Fig3-Aerials\_1949-2019.mxd Date Saved: 17/04/2019


**AECOM**



1:1,250 (when printed at A3)

Legend

 **Site Boundary**




**Figure 3A**  
**AERIAL PHOTO - 1949**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.



\\auad11fp001\AECOM\_Projects\606\60603737\900\_CAD\_GIS\920\_GIS\FIGURES\MXD\60603737-Fig3-Aerials\_1949-2019.mxd Date Saved: 17/04/2019


**AECOM**



1:1,250 (when printed at A3)

Legend

 **Site Boundary**



**Figure 3B**  
**AERIAL PHOTO - 1959**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.




**AECOM**



1:1,250 (when printed at A3)

Legend

 **Site Boundary**



**Figure 3C**  
**AERIAL PHOTO - 1969**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.




**AECOM**



1:1,250 (when printed at A3)

Legend

 Site Boundary



**Figure 3D  
AERIAL PHOTO - 1979**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.




# AECOM



1:1,250 (when printed at A3)

Legend

 Site Boundary



**Figure 3E**  
**AERIAL PHOTO - 1989**

GILLES PLAINS TAFE

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.



\\auad11fp001\AECOM\_Projects\606\160603737\900\_CAD\_GIS\920\_GIS\FIGURES\MXD\60603737-Fig3-Aerials\_1949-2019.mxd Date Saved: 17/04/2019


**AECOM**



1:1,250 (when printed at A3)

Legend

 **Site Boundary**



**Figure 3F**  
**AERIAL PHOTO - 1999**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.




**AECOM**



1:1,250 (when printed at A3)

Legend

 **Site Boundary**



**Figure 3G  
AERIAL PHOTO - 2005**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.




**AECOM**



1:1,250 (when printed at A3)

Legend

 Site Boundary



**Figure 3H  
AERIAL PHOTO - 2009**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.




# AECOM



1:1,250 (when printed at A3)

Legend

 Site Boundary



**Figure 3I**  
**AERIAL PHOTO - 2019**

**GILLES PLAINS TAFE**

**33 BLACKS RD,  
GILLES PLAINS SA 5086**

Data Sources:  
- StreetPro © 2011 Pitney Bowes Software Pty Ltd. All rights reserved.

Disclaimer:  
AECOM has exercised all due care in the preparation of this map. AECOM makes no warranty or representation to the Client or third parties (express or implied) in respect of the information conveyed on this map, particularly with regard to any commercial investment decision made on the basis of this map. Use of this map by the Client or third parties shall be at their own risk, and extracts from this map may only be published with permission of AECOM. This disclaimer must be visible in every copy of this map.

# Appendix I

## SA EPA Section 7 Search

AECOM Australia Pty Ltd  
Level 28  
91 King William Street  
ADELAIDE SA 5000

Contact: Section 7  
Telephone: (08) 8204 2026  
Email: epasection7@sa.gov.au

Contact: Public Register  
Telephone: (08) 8204 9128  
Email: epa.publicregister@sa.gov.au

16 April, 2019

### **EPA STATEMENT TO FORM 1 - CONTRACTS FOR SALE OF LAND OR BUSINESS**

The EPA provides this statement to assist the vendor meet its obligations under section 7(1)(b) of the *Land and Business (Sale and Conveyancing) Act 1994*. A response to the questions prescribed in Schedule 1-Contracts for sale of land or business-forms (Divisions 1 and 2) of the *Land and Business (Sale and Conveyancing) Act 1994* is provided in relation to the land.

I refer to your enquiry concerning the parcel of land comprised in

Title Reference CT Volume 5519 Folio 164

Address Section 788 (H106100), Blacks Road, GILLES PLAINS SA 5086

#### **Schedule – Division 1 – *Land and Business (Sale and Conveyancing) Regulations 2010***

#### **PARTICULARS OF MORTGAGES, CHARGES AND PRESCRIBED ENCUMBRANCES AFFECTING THE LAND**

##### ***7. Environment Protection Act 1993***

Does the EPA hold any of the following details relating to the *Environment Protection Act 1993*:

7.1	Section 59 - Environment performance agreement that is registered in relation to the land.	NO
7.2	Section 93 - Environment protection order that is registered in relation to the land.	NO
7.3	Section 93A - Environment protection order relating to cessation of activity that is registered in relation to the land.	NO
7.4	Section 99 - Clean-up order that is registered in relation to the land.	NO
7.5	Section 100 - Clean-up authorisation that is registered in relation to the land.	NO
7.6	Section 103H - Site contamination assessment order that is registered in relation to the land.	NO
7.7	Section 103J - Site remediation order that is registered in relation to the land.	NO

7.8	Section 103N - Notice of declaration of special management area in relation to the land (due to possible existence of site contamination).	NO
7.9	Section 103P - Notation of site contamination audit report in relation to the land.	NO
7.10	Section 103S - Notice of prohibition or restriction on taking water affected by site contamination in relation to the land.	NO

## **Schedule – Division 2 – *Land and Business (Sale and Conveyancing) Regulations 2010***

### **PARTICULARS RELATING TO ENVIRONMENT PROTECTION**

#### ***3-Licences and exemptions recorded by EPA in public register***

Does the EPA hold any of the following details in the public register:

a)	details of a current licence issued under Part 6 of the <i>Environment Protection Act 1993</i> to conduct, at the land-	
i)	a waste or recycling depot (as referred to in clause 3(3) of Schedule 1 Part A of that Act); or	NO
ii)	activities producing listed wastes (as referred to in clause 3(4) of Schedule 1 Part A of that Act); or	NO
iii)	any other prescribed activity of environmental significance under Schedule 1 of that Act?	NO
b)	details of a licence no longer in force issued under Part 6 of the <i>Environment Protection Act 1993</i> to conduct, at the land-	
i)	a waste or recycling depot (as referred to in clause 3(3) of Schedule 1 Part A of that Act); or	NO
ii)	activities producing listed wastes (as referred to in clause 3(4) of Schedule 1 Part A of that Act); or	NO
iii)	any other prescribed activity of environmental significance under Schedule 1 of that Act?	NO
c)	details of a current exemption issued under Part 6 of the <i>Environment Protection Act 1993</i> from the application of a specified provision of that Act in relation to an activity carried on at the land?	NO
d)	details of an exemption no longer in force issued under Part 6 of the <i>Environment Protection Act 1993</i> from the application of a specified provision of that Act in relation to an activity carried on at the land?	NO
e)	details of a licence issued under the repealed <i>South Australian Waste Management Commission Act 1979</i> to operate a waste depot at the land?	NO
f)	details of a licence issued under the repealed <i>Waste Management Act 1987</i> to operate a waste depot at the land?	NO
g)	details of a licence issued under the repealed <i>South Australian Waste Management Commission Act 1979</i> to produce waste of a prescribed kind (within the meaning of that Act) at the land?	NO

- |    |   |    |
|----|---|----|
| h) | details of a licence issued under the repealed <i>Waste Management Act 1987</i> to produce prescribed waste (within the meaning of that Act) at the land? | NO |
|----|---|----|

**4-Pollution and site contamination on the land - details recorded by the EPA in public register**

Does the EPA hold any of the following details in the public register in relation to the land or part of the land:

- |    |  |    |
|----|--|----|
| a) | details of serious or material environmental harm caused or threatened in the course of an activity (whether or not notified under section 83 of the <i>Environment Protection Act 1993</i> )?   | NO |
| b) | details of site contamination notified to the EPA under section 83A of the <i>Environment Protection Act 1993</i> ?  | NO |
| c) | a copy of a report of an environmental assessment (whether prepared by the EPA or some other person or body and whether or not required under legislation) that forms part of the information required to be recorded in the public register?                          | NO |
| d) | a copy of a site contamination audit report?   | NO |
| e) | details of an agreement for the exclusion or limitation of liability for site contamination to which section 103E of the <i>Environment Protection Act 1993</i> applies?   | NO |
| f) | details of an agreement entered into with the EPA relating to an approved voluntary site contamination assessment proposal under section 103I of the <i>Environment Protection Act 1993</i> ?  | NO |
| g) | details of an agreement entered into with the EPA relating to an approved voluntary site remediation proposal under section 103K of the <i>Environment Protection Act 1993</i> ?   | NO |
| h) | details of a notification under section 103Z(1) of the <i>Environment Protection Act 1993</i> relating to the commencement of a site contamination audit?  | NO |
| i) | details of a notification under section 103Z(2) of the <i>Environment Protection Act 1993</i> relating to the termination before completion of a site contamination audit?   | NO |
| j) | details of records, held by the former <i>South Australian Waste Management Commission</i> under the repealed <i>Waste Management Act 1987</i> , of waste (within the meaning of that Act) having been deposited on the land between 1 January 1983 and 30 April 1995? | NO |

**5-Pollution and site contamination on the land - other details held by EPA**

Does the EPA hold any of the following details in relation to the land or part of the land:

- |    |  |    |
|----|--|----|
| a) | a copy of a report known as a "Health Commission Report" prepared by or on behalf of the <i>South Australian Health Commission</i> (under the repealed <i>South Australian Health Commission Act 1976</i> )?   | NO |
| b) | details (which may include a report of an environmental assessment) relevant to an agreement entered into with the EPA relating to an approved voluntary site contamination assessment proposal under section 103I of the <i>Environment Protection Act 1993</i> ? | NO |
| c) | details (which may include a report of an environmental assessment) relevant to an agreement entered into with the EPA relating to an approved voluntary site remediation proposal under section 103K of the <i>Environment Protection Act 1993</i> ?              | NO |

- |    |  |    |
|----|--|----|
| d) | a copy of a pre-1 July 2009 site audit report?   | NO |
| e) | details relating to the termination before completion of a pre-1 July 2009 site audit? | NO |

All care and diligence has been taken to access the above information from available records. Historical records provided to the EPA concerning matters arising prior to 1 May 1995 are limited and may not be accurate or complete and therefore the EPA cannot confirm the accuracy of the historical information provided.

# Appendix J

## Dangerous Substances Licence Search



2 April 2019

Dr Jennifer de Livera  
RenewalSA  
Riverside Centre  
North Terrace  
ADELAIDE SA 5000

**Licensing, Customer Services Team**

Level 4 World Park A  
33 Richmond Road  
Keswick SA 5035

GPO Box 465  
Adelaide SA 5001

DX 715 Adelaide

**Phone** 1300 365 255

**Email** [licensing.safework@sa.gov.au](mailto:licensing.safework@sa.gov.au)

**ABN** 50-560-588-327

**[www.safework.sa.gov.au](http://www.safework.sa.gov.au)**

Dear Dr de Livera

**DANGEROUS SUBSTANCES LICENCE SEARCH**

**PROPERTY DETAILS: Blacks Road, Gilles Plains**

Further to your application for a Dangerous Substance Search dated 20 March 2019 received for the abovementioned site, I advise that there are no current or historical records for this site.

Yours sincerely

A handwritten signature in black ink, consisting of a stylized, flowing script that appears to be the name of the Manager.

**MANAGER  
CUSTOMER SERVICES TEAM  
SAFEWORK SA**